

# **MM-9032**

### **High-Purity Standards**

### Catalogue number: MM-9032

Version No: 1.1 Safety Data Sheet according to OSHA HazCom Standard (2012) requirements

# Chemwatch Hazard Alert Code: 4

Issue Date: 06/01/2017 Print Date: 06/01/2017 S.GHS.USA.EN

# **SECTION 1 IDENTIFICATION**

### **Product Identifier**

Product name	MM-9032
Synonyms	MM-9032
Proper shipping name	Corrosive liquid, acidic, inorganic, n.o.s.
Other means of identification	MM-9032

### Recommended use of the chemical and restrictions on use

Relevant identified uses Use according to manufacturer's directions.

### Name, address, and telephone number of the chemical manufacturer, importer, or other responsible party

Registered company name	High-Purity Standards
Address	PO Box 41727 SC 29423 United States
Telephone	843-767-7900
Fax	843-767-7906
Website	highpuritystandards.com
Email	Not Available

### Emergency phone number

Association / Organisation	INFOTRAC
Emergency telephone numbers	
Other emergency telephone numbers	

### **SECTION 2 HAZARD(S) IDENTIFICATION**

#### Classification of the substance or mixture

Classification       Skin Sensitizer Category 1, Specific target organ toxicity - repeated exposure Category 1, Respiratory Sensitizer Category 1, Germ cell mutagenicity         Classification       Category 2, Carcinogenicity Category 1A, Reproductive Toxicity Category 1B, Acute Aquatic Hazard Category 2, Chronic Aquatic Hazard Category 2, Mer         Corrosion Category 1, Skin Corrosion/Irritation Category 1A	tal
--	-----

# Label elements

Hazard pictogram(s)	L. Contraction	¥2

SIGNAL WORD	DANGER		
Hazard statement(s)			
H317	May cause an allergic skin reaction.		
H372	H372 Causes damage to organs through prolonged or repeated exposure.		
H334	May cause allergy or asthma symptoms or breathing difficulties if inhaled.		
H341	Suspected of causing genetic defects.		

H350 May cause cancer.

Chemwatch: 9-404998		Page <b>2</b> of <b>11</b>	Issue Date: 06/01/201
Catalogue number: <b>MM-9032</b> /ersion No: <b>1.1</b>	/	MM-9032	Print Date: 06/01/201
H360	May damage fertility or the unborn child.		
H411	Toxic to aquatic life with long lasting effects.		
H290			
H314	Causes severe skin burns and eye damage.		
Hazard(s) not otherwise s Not Applicable	specified		
Precautionary statement(	s) Prevention		
P201	Obtain special instructions before use.		
Precautionary statement(	s) Response		
P301+P330+P331	IF SWALLOWED: Rinse mouth. Do NOT induce	e vomiting.	
Precautionary statement(			
P405	Store locked up.		
Precautionary statement(	s) Disposal		
P501	Dispose of contents/container in accordance wit	h local regulations.	
SECTION 3 COMPOSITI	ON / INFORMATION ON INGREDIENT	'S	
Substances See section below for compositi	on of Mixtures		
Mixtures			
CAS No	%[weight]	Name	
7697-37-2	1	nitric acid	
7732-18-5	balance	water	
13138-45-9	5	nickel(II) nitrate	
SECTION 4 FIRST-AID M	IEASURES		
Description of first aid m	easures		
•			

Eye Contact	If this product comes in contact with the eyes: <ul> <li>Immediately hold eyelids apart and flush the eye continuously with running water.</li> <li>Ensure complete irrigation of the eye by keeping eyelids apart and away from eye and moving the eyelids by occasionally lifting the upper and lower lids.</li> <li>Continue flushing until advised to stop by the Poisons Information Centre or a doctor, or for at least 15 minutes.</li> <li>Transport to hospital or doctor without delay.</li> <li>Removal of contact lenses after an eye injury should only be undertaken by skilled personnel.</li> </ul>
Skin Contact	<ul> <li>If skin or hair contact occurs:</li> <li>Immediately flush body and clothes with large amounts of water, using safety shower if available.</li> <li>Quickly remove all contaminated clothing, including footwear.</li> <li>Wash skin and hair with running water. Continue flushing with water until advised to stop by the Poisons Information Centre.</li> <li>Transport to hospital, or doctor.</li> </ul>
Inhalation	<ul> <li>If furnes or combustion products are inhaled remove from contaminated area.</li> <li>Lay patient down. Keep warm and rested.</li> <li>Prostheses such as false teeth, which may block airway, should be removed, where possible, prior to initiating first aid procedures.</li> <li>Apply artificial respiration if not breathing, preferably with a demand valve resuscitator, bag-valve mask device, or pocket mask as trained. Perform CPR if necessary.</li> <li>Transport to hospital, or doctor, without delay.</li> <li>Inhalation of vapours or aerosols (mists, furnes) may cause lung oedema.</li> <li>Corrosive substances may cause lung damage (e.g. lung oedema, fluid in the lungs).</li> <li>As this reaction may be delayed up to 24 hours after exposure, affected individuals need complete rest (preferably in semi-recumbent posture) and must be kept under medical observation, the administration of a spray containing a dexamethasone derivative or beclomethasone derivative may be considered.</li> <li>This must definitely be left to a doctor or person authorised by him/her.</li> <li>(ICSC13719)</li> </ul>
Ingestion	<ul> <li>For advice, contact a Poisons Information Centre or a doctor at once.</li> <li>Urgent hospital treatment is likely to be needed.</li> <li>If swallowed do NOT induce vomiting.</li> <li>If vomiting occurs, lean patient forward or place on left side (head-down position, if possible) to maintain open airway and prevent aspiration.</li> <li>Observe the patient carefully.</li> <li>Never give liquid to a person showing signs of being sleepy or with reduced awareness; i.e. becoming unconscious.</li> <li>Give water to rinse out mouth, then provide liquid slowly and as much as casualty can comfortably drink.</li> <li>Transport to hospital or doctor without delay.</li> </ul>

Most important symptoms and effects, both acute and delayed

See Section 11

Chemwatch: 9-404998	Page <b>3</b> of <b>11</b>		Issue Date: 06/01/2017
Catalogue number: MM-9032	MM-9032	$\overline{}$	Print Date: 06/01/2017
Version No: 1.1			

#### Indication of any immediate medical attention and special treatment needed

For acute or short term repeated exposures to strong acids:

- Airway problems may arise from laryngeal edema and inhalation exposure. Treat with 100% oxygen initially.
- Respiratory distress may require cricothyroidotomy if endotracheal intubation is contraindicated by excessive swelling
- Intravenous lines should be established immediately in all cases where there is evidence of circulatory compromise.
- + Strong acids produce a coagulation necrosis characterised by formation of a coagulum (eschar) as a result of the dessicating action of the acid on proteins in specific tissues.

INGESTION:

- ▶ Immediate dilution (milk or water) within 30 minutes post ingestion is recommended.
- DO NOT attempt to neutralise the acid since exothermic reaction may extend the corrosive injury.
- Be careful to avoid further vomit since re-exposure of the mucosa to the acid is harmful. Limit fluids to one or two glasses in an adult.
- Charcoal has no place in acid management.
- Some authors suggest the use of lavage within 1 hour of ingestion.

SKIN:

- Skin lesions require copious saline irrigation. Treat chemical burns as thermal burns with non-adherent gauze and wrapping.
- Deep second-degree burns may benefit from topical silver sulfadiazine.

#### EYE:

- Eye injuries require retraction of the eyelids to ensure thorough irrigation of the conjuctival cul-de-sacs. Irrigation should last at least 20-30 minutes. DO NOT use neutralising agents or any other additives. Several litres of saline are required.
- Cycloplegic drops, (1% cyclopentolate for short-term use or 5% homatropine for longer term use) antibiotic drops, vasoconstrictive agents or artificial tears may be indicated dependent on the severity of the injury.
- Steroid eye drops should only be administered with the approval of a consulting ophthalmologist).

[Ellenhorn and Barceloux: Medical Toxicology]

### **SECTION 5 FIRE-FIGHTING MEASURES**

### Extinguishing media

There is no restriction on the type of extinguisher which may be used.

Use extinguishing media suitable for surrounding area.

### Special hazards arising from the substrate or mixture

Fire Incompatibility None known.

### Special protective equipment and precautions for fire-fighters

Fire Fighting	
Fire/Explosion Hazard	<ul> <li>Non combustible.</li> <li>Not considered to be a significant fire risk.</li> <li>Acids may react with metals to produce hydrogen, a highly flammable and explosive gas.</li> <li>Heating may cause expansion or decomposition leading to violent rupture of containers.</li> <li>May emit corrosive, poisonous fumes. May emit acrid smoke.</li> </ul>

### SECTION 6 ACCIDENTAL RELEASE MEASURES

# Personal precautions, protective equipment and emergency procedures

See section 8

#### Environmental precautions

See section 12

#### Methods and material for containment and cleaning up

Minor Spills	<ul> <li>Drains for storage or use areas should have retention basins for pH adjustments and dilution of spills before discharge or disposal of material.</li> <li>Check regularly for spills and leaks.</li> <li>Clean up all spills immediately.</li> <li>Avoid breathing vapours and contact with skin and eyes.</li> <li>Control personal contact with the substance, by using protective equipment.</li> <li>Contain and absorb spill with sand, earth, inert material or vermiculite.</li> <li>Wipe up.</li> <li>Place in a suitable, labelled container for waste disposal.</li> </ul>
Major Spills	#

Personal Protective Equipment advice is contained in Section 8 of the SDS.

# SECTION 7 HANDLING AND STORAGE

### Precautions for safe handling

Safe handling	<ul> <li>Avoid all personal contact, including inhalation.</li> <li>Wear protective clothing when risk of exposure occurs.</li> <li>Use in a well-ventilated area.</li> <li>WARNING: To avoid violent reaction, ALWAYS add material to water and NEVER water to material.</li> <li>Avoid smoking, naked lights or ignition sources.</li> <li>Avoid contact with incompatible materials.</li> <li>When handling, DO NOT eat, drink or smoke.</li> <li>Keep containers securely sealed when not in use.</li> <li>Avoid physical damage to containers.</li> <li>Always wash hands with soap and water after handling.</li> <li>Work clothes should be laundered separately. Launder contaminated clothing before re-use.</li> </ul>

Chemwatch: 9-404998		Page <b>4</b> of <b>11</b>		Issue Date: 06/01/2017
Catalogue number: <b>MM-9032</b>		MM-9032		Print Date: 06/01/2017
Version No: 1.1				
	<ul> <li>Use good occupational work practice.</li> <li>Observe manufacturer's storage and handli</li> <li>Atmosphere should be regularly checked as</li> </ul>	5	n this SDS. to ensure safe working conditions are maintained.	
Other information	<ul> <li>Store in original containers.</li> <li>Keep containers securely sealed.</li> <li>Store in a cool, dry, well-ventilated area.</li> <li>Store away from incompatible materials and</li> <li>Protect containers against physical damage</li> <li>Observe manufacturer's storage and handl</li> </ul>	e and check regularly for leaks.	n this SDS.	
Conditions for safe storag	e, including any incompatibilities			
	<ul> <li>DO NOT use aluminium or galvanised con</li> <li>Check regularly for spills and leaks</li> <li>Lined metal can, lined metal pail/ can.</li> </ul>	tainers		

Suitable container	<ul> <li>Lined metal can, lined metal pail/ can.</li> <li>Plastic pail.</li> <li>Polyliner drum.</li> <li>Packing as recommended by manufacturer.</li> <li>Check all containers are clearly labelled and free from leaks.</li> <li>For low viscosity materials</li> <li>Drums and jerricans must be of the non-removable head type.</li> <li>Where a can is to be used as an inner package, the can must have a screwed enclosure.</li> <li>For materials with a viscosity of at least 2680 cSt. (23 deg. C) and solids (between 15 C deg. and 40 deg C.):</li> <li>Removable head packaging;</li> <li>Cans with friction closures and</li> <li>low pressure tubes and cartridges may be used.</li> <li>-</li> <li>Where combination packages are used, and the inner packages are of glass, porcelain or stoneware, there must be sufficient inert cushioning material in contact with inner and outer packages unless the outer packaging is a close fitting moulded plastic box and the substances are not incompatible with the plastic.</li> </ul>
Storage incompatibility	<ul> <li>Inorganic acids are generally soluble in water with the release of hydrogen ions. The resulting solutions have pH's of less than 7.0.</li> <li>Inorganic acids neutralise chemical bases (for example: amines and inorganic hydroxides) to form salts - neutralisation can generate dangerously large amounts of heat in small spaces.</li> <li>The dissolution of inorganic acids in water or the dilution of their concentrated solutions with additional water may generate significant heat.</li> <li>The addition of water to inorganic acids often generates sufficient heat in the small region of mixing to cause some of the water to boil explosively. The resulting "bumping" can spatter the acid.</li> <li>Inorganic acids react with active metals, including such structural metals as aluminum and iron, to release hydrogen, a flammable gas.</li> <li>Inorganic acids react with active metals, including such structural metals as aluminum and iron, to release hydrogen, a flammable gas.</li> <li>Inorganic acids react with active metals, including such structural metals as aluminum and iron, to release hydrogen, a flammable gas.</li> <li>Inorganic acids react with cyanide compounds to release gaseous hydrogen cyanide.</li> <li>Inorganic acids generate flammable and/or toxic gases in contact with dithiocarbamates, isocyanates, mercaptans, nitrides, nitriles, sulfides, and strong reducing agents. Additional gas-generating reactions occur with sulfites, nitrites, thiosulfates (to give H2S and SO3), dithionites (SO2), and even carbonates.</li> <li>Acids often catalyse (increase the rate of) chemical reactions.</li> <li>WARNING: Avoid or control reaction with peroxides. All <i>transition metal</i> peroxides should be considered as potentially explosive. For example transition metal complexes of alkyl hydroperoxides may decompose explosively.</li> <li>The pi-complexes formed between chromium(0), vanadium(0) and other transition metals (haloarene-metal complexes) and mono-or poly-fluorobenzene show extreme sensitivity to heat and are explosi</li></ul>

# SECTION 8 EXPOSURE CONTROLS / PERSONAL PROTECTION

# **Control parameters**

# OCCUPATIONAL EXPOSURE LIMITS (OEL)

# INGREDIENT DATA

Source	Ingredient	Material name	TWA	STEL	Peak	Notes
US OSHA Permissible Exposure Levels (PELs) - Table Z1	nitric acid	Nitric acid	5 mg/m3 / 2 ppm	10 mg/m3 / 4 ppm	Not Available	TLV® Basis: URT & eye irr; dental erosion
US NIOSH Recommended Exposure Limits (RELs)	nitric acid	Aqua fortis, Engravers acid, Hydrogen nitrate, Red fuming nitric acid (RFNA), White fuming nitric acid (WFNA)	5 mg/m3 / 2 ppm	4 ppm	Not Available	Not Available
US ACGIH Threshold Limit Values (TLV)	nitric acid	Nitric acid	2 ppm	Not Available	Not Available	Not Available

EMERGENCY LIMITS

Ingredient	Material name	TEEL-1		TEEL-2	TEEL-3
nitric acid	Nitric acid	Not Available		Not Available	Not Available
nickel(II) nitrate	Nickel(II) nitrate; (Nickelous nitrate)	0.93 mg/m3		10 mg/m3	61 mg/m3
nickel(II) nitrate	Nickel(II) nitrate hexahydrate	1.5 mg/m3		53 mg/m3	320 mg/m3
Ingredient	Original IDLH		Revised IDLH		
nitric acid	100 ppm		25 ppm		
water	Not Available		Not Available		
nickel(II) nitrate	N.E. / N.E.		10 mg/m3		

### Exposure controls

Appropriate engineering

gineering Engineering controls are used to remove a hazard or place a barrier between the worker and the hazard. Well-designed engineering controls can be highly

Chemwatch: 9-404998	Page <b>5</b> of <b>11</b>	Issue Date: 06/01/2017
Catalogue number: MM-9032	MM-9032	Print Date: 06/01/2017
Version No: 1.1		

	<b>1 1 1 1 1 1 1 1 1 1</b>		
	effective in protecting workers and will typically be independent of worker interactions to provide this I The basic types of engineering controls are: Process controls which involve changing the way a job activity or process is done to reduce the risk. Enclosure and/or isolation of emission source which keeps a selected hazard "physically" away from "removes" air in the work environment. Ventilation can remove or dilute an air contaminant if designed the particular process and chemical or contaminant in use. Employers may need to use multiple types of controls to prevent employee overexposure.	the worker and ventilation that stra	
	Local exhaust ventilation usually required. If risk of overexposure exists, wear approved respirator. C Supplied-air type respirator may be required in special circumstances. Correct fit is essential to ens An approved self contained breathing apparatus (SCBA) may be required in some situations. Provide adequate ventilation in warehouse or closed storage area. Air contaminants generated in the turn, determine the "capture velocities" of fresh circulating air required to effectively remove the conta	ure adequate protection. e workplace possess varying "esca	
	Type of Contaminant:		Air Speed:
	solvent, vapours, degreasing etc., evaporating from tank (in still air).		0.25-0.5 m/s (50-100 f/min.)
	aerosols, fumes from pouring operations, intermittent container filling, low speed conveyer transfer acid fumes, pickling (released at low velocity into zone of active generation)	s, welding, spray drift, plating	0.5-1 m/s (100-200 f/min.)
controls	direct spray, spray painting in shallow booths, drum filling, conveyer loading, crusher dusts, gas dis zone of rapid air motion)	scharge (active generation into	1-2.5 m/s (200-500 f/min.)
	grinding, abrasive blasting, tumbling, high speed wheel generated dusts (released at high initial ve air motion).	locity into zone of very high rapid	2.5-10 m/s (500-2000 f/min.)
	Within each range the appropriate value depends on:		
	Lower end of the range	Upper end of the range	
	1: Room air currents minimal or favourable to capture	1: Disturbing room air currents	
	2: Contaminants of low toxicity or of nuisance value only.	2: Contaminants of high toxicity	
	3: Intermittent, low production.	3: High production, heavy use	
	4: Large hood or large air mass in motion	4: Small hood-local control only	
	Simple theory shows that air velocity falls rapidly with distance away from the opening of a simple ext of distance from the extraction point (in simple cases). Therefore the air speed at the extraction point distance from the contaminating source. The air velocity at the extraction fan, for example, should be	raction pipe. Velocity generally dec should be adjusted, accordingly, a	after reference to
	of distance from the extraction point (in simple cases). Therefore the air speed at the extraction point	raction pipe. Velocity generally dec should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/n ons, producing performance defici	after reference to nin) for extraction of ts within the extraction
Personal protection	of distance from the extraction point (in simple cases). Therefore the air speed at the extraction point distance from the contaminating source. The air velocity at the extraction fan, for example, should be solvents generated in a tank 2 meters distant from the extraction point. Other mechanical considerati	raction pipe. Velocity generally dec should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/n ons, producing performance defici	after reference to nin) for extraction of ts within the extraction
Personal protection	of distance from the extraction point (in simple cases). Therefore the air speed at the extraction point distance from the contaminating source. The air velocity at the extraction fan, for example, should be solvents generated in a tank 2 meters distant from the extraction point. Other mechanical considerati	raction pipe. Velocity generally dec should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/n ons, producing performance defici n extraction systems are installed of desirable, as in laboratories; specta a danger of splashing, or if the ma goggles must be properly fitted. protection of eyes; these afford fac ants. A written policy document, da a review of lens absorption and ac trained in their removal and suitab contact lens as soon as practicable	after reference to hin) for extraction of ts within the extraction or used. acles are not sufficient terial may be under be protection. escribing the wearing of sorption for the class of ble. Lens should be rem
	<ul> <li>of distance from the extraction point (in simple cases). Therefore the air speed at the extraction point distance from the contaminating source. The air velocity at the extraction fan, for example, should be solvents generated in a tank 2 meters distant from the extraction point. Other mechanical considerati apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more where</li> <li>Safety glasses with unperforated side shields may be used where continuous eye protection is or where complete eye protection is needed such as when handling bulk-quantities, where there is pressure.</li> <li>Chemical goggles.whenever there is a danger of the material coming in contact with the eyes; i Full face shield (20 cm, 8 in minimum) may be required for supplementary but never for primary.</li> <li>Alternatively a gas mask may replace splash goggles and face shields.</li> <li>Contact lenses may pose a special hazard; soft contact lenses may absorb and concentrate irrit lenses or restrictions on use, should be created for each workplace or task. This should include chemicals in use and an account of injury experience. Medical and first-aid personnel should be readily available. In the event of chemical exposure, begin eye irrigation immediately and remove at the first signs of eye redness or irritation - lens should be removed in a clean environment only</li> </ul>	raction pipe. Velocity generally dec should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/n ons, producing performance defici n extraction systems are installed of desirable, as in laboratories; specta a danger of splashing, or if the ma goggles must be properly fitted. protection of eyes; these afford fac ants. A written policy document, da a review of lens absorption and ac trained in their removal and suitab contact lens as soon as practicable	after reference to hin) for extraction of ts within the extraction or used. acles are not sufficient terial may be under be protection. escribing the wearing of sorption for the class of ble. Lens should be rem
Eye and face protection	<ul> <li>of distance from the extraction point (in simple cases). Therefore the air speed at the extraction point distance from the contaminating source. The air velocity at the extraction fan, for example, should be solvents generated in a tank 2 meters distant from the extraction point. Other mechanical considerati apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more where</li> <li>Safety glasses with unperforated side shields may be used where continuous eye protection is needed such as when handling bulk-quantities, where there is pressure.</li> <li>Chemical goggles.whenever there is a danger of the material coming in contact with the eyes; 9</li> <li>Full face shield (20 cm, 8 in minimum) may be required for supplementary but never for primary</li> <li>Alternatively a gas mask may replace splash goggles and face shields.</li> <li>Contact lenses may pose a special hazard; soft contact lenses may absorb and concentrate irrit lenses or restrictions on use, should be created for each workplace or task. This should include chemicals in use and an account of injury experience. Medical and first-aid personnel should be readily available. In the event of chemical exposure, begin eye irrigation immediately and remove at the first signs of eye redness or irritation - lens should be removed in a clean environment only Current Intelligence Bulletin 59], [AS/NZS 1336 or national equivalent]</li> </ul>	raction pipe. Velocity generally dec should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/n ons, producing performance defici extraction systems are installed of desirable, as in laboratories; specta a danger of splashing, or if the ma goggles must be properly fitted. protection of eyes; these afford fac ants. A written policy document, de a review of lens absorption and ac trained in their removal and suitab contact lens as soon as practicably a fler workers have washed hands ring boots.	after reference to hin) for extraction of ts within the extraction or used. acles are not sufficient terial may be under accession of the class of le equipment should be le. Lens should be rem s thoroughly. [CDC NIC
Eye and face protection	<ul> <li>of distance from the extraction point (in simple cases). Therefore the air speed at the extraction point distance from the contaminating source. The air velocity at the extraction fan, for example, should be solvents generated in a tank 2 meters distant from the extraction point. Other mechanical considerati apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more where</li> <li>Safety glasses with unperforated side shields may be used where continuous eye protection is a where complete eye protection is needed such as when handling bulk-quantities, where there is pressure.</li> <li>Chemical goggles.whenever there is a danger of the material coming in contact with the eyes; 9 Full face shield (20 cm, 8 in minimum) may be required for supplementary but never for primary</li> <li>Alternatively a gas mask may replace splash goggles and face shields.</li> <li>Contact lenses may pose a special hazard; soft contact lenses may absorb and concentrate infit lenses or restrictions on use, should be created for each workplace or task. This should include chemicals in use and an account of injury experience. Medical and first-aid personnel should be readily available. In the event of chemical exposure, begin eye irrigation immediately and remove at the first signs of eye redness or irritation - lens should be removed in a clean environment only Current Intelligence Bulletin 59], [AS/NZS 1336 or national equivalent]</li> <li>See Hand protection below</li> <li>Elbow length PVC gloves</li> <li>When handling corrosive liquids, wear trousers or overalls outside of boots, to avoid spills enter NOTE:</li> <li>The material may produce skin sensitisation in predisposed individuals. Care must be taken, where all possible skin contact.</li> </ul>	raction pipe. Velocity generally dec should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/n ons, producing performance defici extraction systems are installed of desirable, as in laboratories; specta a danger of splashing, or if the ma goggles must be properly fitted. protection of eyes; these afford fac ants. A written policy document, de a review of lens absorption and ac trained in their removal and suitab contact lens as soon as practicably a fler workers have washed hands ring boots.	after reference to hin) for extraction of ts within the extraction or used. acles are not sufficient terial may be under exprotection. escribing the wearing of sloe equipment should be le. Lens should be rem s thoroughly. [CDC NIC
Eye and face protection Skin protection Hands/feet protection	<ul> <li>of distance from the extraction point (in simple cases). Therefore the air speed at the extraction point distance from the contaminating source. The air velocity at the extraction fan, for example, should be solvents generated in a tank 2 meters distant from the extraction point. Other mechanical considerati apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more where</li> <li>Safety glasses with unperforated side shields may be used where continuous eye protection is or where complete eye protection is needed such as when handling bulk-quantities, where there is pressure.</li> <li>Chemical goggles.whenever there is a danger of the material coming in contact with the eyes; generatively a gas mask may replace splash goggles and face shields.</li> <li>Contact lenses may pose a special hazard; soft contact lenses may absorb and concentrate intil lenses or restrictions on use, should be created for each workplace or task. This should include chemicals in use and an account of injury experience. Medical and first-aid personnel should be readily available. In the event of chemical exposure, begin eye irrigation immediately and remove at the first signs of eye redness or irritation - lens should be removed in a clean environment only Current Intelligence Bulletin 59], [AS/NZS 1336 or national equivalent]</li> <li>See Hand protection below</li> <li>Elbow length PVC gloves</li> <li>When handling corrosive liquids, wear trousers or overalls outside of boots, to avoid spills enter NOTE:</li> <li>The material may produce skin sensitisation in predisposed individuals. Care must be taken, whe all possible skin contact.</li> <li>Contaminated leather items, such as shoes, belts and watch-bands should be removed and desting the store should be removed and be removed and be removed and desting the store should be removed and be stores or spills enter the stores or the store should be removed and be removed and be removed and be removed and desting the store should be removed</li></ul>	raction pipe. Velocity generally dec should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/n ons, producing performance defici extraction systems are installed of desirable, as in laboratories; specta a danger of splashing, or if the ma goggles must be properly fitted. protection of eyes; these afford fac ants. A written policy document, de a review of lens absorption and ac trained in their removal and suitab contact lens as soon as practicably a fler workers have washed hands ring boots.	after reference to nin) for extraction of ts within the extraction or used. acles are not sufficient terial may be under exprotection. escribing the wearing of sle equipment should be lee equipment should be rems thoroughly. [CDC NIC

# Respiratory protection

Type A Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

# SECTION 9 PHYSICAL AND CHEMICAL PROPERTIES

# Information on basic physical and chemical properties

Appearance Colourless

Discribed state	1 feeded	Deletive density (Meter 4)	Net Augustele
Physical state	Liquid	Relative density (Water = 1)	Not Available
Odour	Not Available	Partition coefficient n-octanol / water	Not Available
Odour threshold	Not Available	Auto-ignition temperature (°C)	Not Available
pH (as supplied)	Not Available	Decomposition temperature	Not Available
Melting point / freezing point (°C)	Not Available	Viscosity (cSt)	Not Available
Initial boiling point and boiling range (°C)	Not Available	Molecular weight (g/mol)	Not Available
Flash point (°C)	Not Available	Taste	Not Available
Evaporation rate	Not Available	Explosive properties	Not Available
Flammability	Not Available	Oxidising properties	Not Available
Upper Explosive Limit (%)	Not Available	Surface Tension (dyn/cm or mN/m)	Not Available
Lower Explosive Limit (%)	Not Available	Volatile Component (%vol)	Not Available
Vapour pressure (kPa)	Not Available	Gas group	Not Available
Solubility in water (g/L)	Miscible	pH as a solution (1%)	Not Available
Vapour density (Air = 1)	Not Available	VOC g/L	Not Available

# SECTION 10 STABILITY AND REACTIVITY

Reactivity	See section 7
Chemical stability	Contact with alkaline material liberates heat
Possibility of hazardous reactions	See section 7
Conditions to avoid	See section 7
Incompatible materials	See section 7
Hazardous decomposition products	See section 5

# SECTION 11 TOXICOLOGICAL INFORMATION

# Information on toxicological effects

Inhaled	The material can cause respiratory irritation in some persons. The body's resp Corrosive acids can cause irritation of the respiratory tract, with coughing, choir nausea and weakness. The material has <b>NOT</b> been classified by EC Directives or other classification animal or human evidence.			
Ingestion	Ingestion of acidic corrosives may produce burns around and in the mouth, the throat and oesophagus. Immediate pain and difficulties in swallowing and speaking may also be evident. The material has <b>NOT</b> been classified by EC Directives or other classification systems as "harmful by ingestion". This is because of the lack of corrobo animal or human evidence.			
Skin Contact	Skin contact with acidic corrosives may result in pain and burns; these may be Skin contact is not thought to have harmful health effects (as classified under f through wounds, lesions or abrasions. Open cuts, abraded or irritated skin should not be exposed to this material Entry into the blood-stream, through, for example, cuts, abrasions or lesions, m of the material and ensure that any external damage is suitably protected.			
Eye	If applied to the eyes, this material causes severe eye damage. Direct eye contact with acid corrosives may produce pain, tears, sensitivity to light and burns. Mild burns of the epithelia generally recover rapidly and completely.			
Chronic	and inflammation of lung tissue often occurs. Studies show that inhaling this substance for over a long period (e.g. in an occ Long-term exposure to respiratory irritants may result in airways disease, invol Strong evidence exists that this substance may cause irreversible mutations (tt Inhaling this product is more likely to cause a sensitisation reaction in some per Skin contact with the material is more likely to cause a sensitisation reaction in for Toxic: danger of serious damage to health by prolonged exposure through inhar This material can cause serious damage if one is exposed to it for long periods defects. Ample evidence exists, from results in experimentation, that developmental disc Laboratory (in vitro) and animal studies show, exposure to the material may re- mutation. Substance accumulation, in the human body, may occur and may cause some of Nickel dusts, furmes and salts are potent contact allergens and sensitisers pro-	ving difficulty breathing and related whole-body problems. hough not lethal) even following a single exposure. rsons compared to the general population. some persons compared to the general population. lation. s. It can be assumed that it contains a substance which can produce severe orders are directly caused by human exposure to the material. sult in a possible risk of irreversible effects, with the possibility of producing concern following repeated or long-term occupational exposure.		
MM-9032	ΤΟΧΙCΙΤΥ	IRRITATION		

Chemwatch: 9-404998

MM-9032

	Not Available	Not Available	
nitric acid	TOXICITY Inhalation (rat) LC50: 625 ppm/1h*t <sup>[2]</sup>		IRRITATION Not Available
water	TOXICITY Not Available	IRRITATION Not Available	
nickel(II) nitrate	TOXICITY Oral (rat) LD50: 275 mg/kg <sup>[1]</sup>		RITATION Available
Legend:	<ol> <li>Value obtained from Europe ECHA Registered Substances - Acute toxicity 2. extracted from RTECS - Register of Toxic Effect of chemical Substances</li> </ol>	* Value obtained from manufact	urer's SDS. Unless otherwise specified data

NITRIC ACID	Asthma-like symptoms may continue for months or even years after exposure to the material ends. For acid mists, aerosols, vapours Test results suggest that eukaryotic cells are susceptible to genetic damage when the pH falls to about 6.5. The material may produce severe irritation to the eye causing pronounced inflammation. The material may produce respiratory tract irritation, and result in damage to the lung including reduced lung function. The material may cause severe skin irritation after prolonged or repeated exposure and may produce on contact skin redness, swelling, the production of vesicles, scaling and thickening of the skin. Oral (?) LD50: 50-500 mg/kg * [Various Manufacturers]						
WATER	No significant acute toxicological data identified in literature	search.					
NICKEL(II) NITRATE	The following information refers to contact allergens as a group and may not be specific to this product. Allergic reactions involving the respiratory tract are usually due to interactions between IgE antibodies and allergens and occur rapidly. Attention should be paid to atopic diathesis, characterised by increased susceptibility to nasal inflammation, asthma and eczema. Exogenous allergic alveolitis is induced essentially by allergen specific immune-complexes of the IgG type; cell-mediated reactions (T lymphocytes) may be involved.						
Acute Toxicity	$\otimes$	Carcinogenicity	✓				
Skin Irritation/Corrosion	✓ Reproductivity ✓						
Serious Eye Damage/Irritation	STOT - Single Exposure						
Respiratory or Skin sensitisation	✓ STOT - Repeated Exposure						
Mutagenicity	✓	Aspiration Hazard					
Legend: X – Data available but does not fill the criteria for classification - Data available to make classification							

# $\bigcirc$ – Data Not Available to make classification

# SECTION 12 ECOLOGICAL INFORMATION

Toxicity ENDPOINT **TEST DURATION (HR)** SPECIES VALUE SOURCE MM-9032 Not Applicable Not Applicable Not Applicable Not Applicable Not Applicable ENDPOINT TEST DURATION (HR) SPECIES VALUE SOURCE nitric acid NOEC 107mg/L 16 Crustacea 4 ENDPOINT **TEST DURATION (HR)** SPECIES VALUE SOURCE water Not Applicable Not Applicable Not Applicable Not Applicable Not Applicable ENDPOINT TEST DURATION (HR) SPECIES VALUE SOURCE LC50 Fish 0.4mg/L 2 96 EC50 48 Crustacea 0.1455mg/L 2 nickel(II) nitrate EC50 72 0.0407mg/L 2 Algae or other aquatic plants EC50 720 Crustacea 0.0062mg/L 2 NOEC 72 Algae or other aquatic plants 0.0035mg/L 2 Extracted from 1. IUCLID Toxicity Data 2. Europe ECHA Registered Substances - Ecotoxicological Information - Aquatic Toxicity 3. EPIWIN Suite V3.12 Legend: (QSAR) - Aquatic Toxicity Data (Estimated) 4. US EPA, Ecotox database - Aquatic Toxicity Data 5. ECETOC Aquatic Hazard Assessment Data 6. NITE (Japan) - Bioconcentration Data 7. METI (Japan) - Bioconcentration Data 8. Vendor Data

Chemwatch: 9-404998	Page <b>8</b> of <b>11</b>		Issue Date: 06/01/2017
Catalogue number: MM-9032	MM-9032	$\overline{}$	Print Date: 06/01/2017
Version No: 1.1			

Toxic to aquatic organisms, may cause long-term adverse effects in the aquatic environment.

Do NOT allow product to come in contact with surface waters or to intertidal areas below the mean high water mark. Do not contaminate water when cleaning equipment or disposing of equipment wash-waters.

Wastes resulting from use of the product must be disposed of on site or at approved waste sites. Ecotoxicity:

The tolerance of water organisms towards pH margin and variation is diverse. Recommended pH values for test species listed in OECD guidelines are between 6.0 and almost 9. Acute testing

with fish showed 96h-LC50 at about pH 3.5 For Nickel: Transport and distribution of nickel particulates between different environmental compartments, is strongly influenced by particle size. Fine particulate matter has a longer residence time in the environment and is carried a long distance from its source; larger particles are deposited near the emission source.

Atmospheric Fate: Atmospheric residence time for nickel particulates is estimated to be 5.4-7.9 days.

Aquatic Fate: Drinking Water Standards: Nickel 50 ug/l (UK max.) 20 ug/l (WHO guideline).

Terrestrial Fate: Water solubility and bioavailability is affected by soil pH; decrease in pH generally mobilizes nickel, thus acid rain can mobilize nickel from the soil and increase nickel concentrations in ground water. Soil Guidelines - Dutch Criteria: 35 mg/kg (target) 210 mg/kg (intervention).

Ecotoxicity: Nickel bioaccumulates in the food chain but is not bioconcentrated.

Prevent, by any means available, spillage from entering drains or water courses.

DO NOT discharge into sewer or waterways

### Persistence and degradability

Ingredient	Persistence: Water/Soil	Persistence: Air
water	LOW	LOW

### **Bioaccumulative potential**

Ingredient	Bioaccumulation	
water	LOW (LogKOW = -1.38)	

### Mobility in soil

Ingredient	Mobility
water	LOW (KOC = 14.3)

# SECTION 13 DISPOSAL CONSIDERATIONS

### Waste treatment methods

	Containers may still present a chemical hazard/ danger when empty.
	Return to supplier for reuse/ recycling if possible.
	Otherwise:
	If container can not be cleaned sufficiently well to ensure that residuals do not remain or if the container cannot be used to store the same product, then puncture containers, to prevent re-use, and bury at an authorised landfill.
	Where possible retain label warnings and SDS and observe all notices pertaining to the product.
Product / Packaging	▶ Recycle wherever possible.
disposal	<ul> <li>Consult manufacturer for recycling options or consult local or regional waste management authority for disposal if no suitable treatment or disposal facility can be identified.</li> </ul>
	<ul> <li>Treat and neutralise at an approved treatment plant. Treatment should involve: Neutralisation with soda-ash or soda-lime followed by: burial in a land-fill specifically licensed to accept chemical and / or pharmaceutical wastes or Incineration in a licensed apparatus (after admixture with suitable combustible material).</li> </ul>
	Decontaminate empty containers with 5% aqueous sodium hydroxide or soda ash, followed by water. Observe all label safeguards until containers are cleaned and destroyed.

# **SECTION 14 TRANSPORT INFORMATION**

### Labels Required

	No. of the second secon
Marine Pollutant	

### Land transport (DOT)

UN number	3264					
UN proper shipping name	prrosive liquid, acidic, inorganic, n.o.s.					
Transport hazard class(es)	Class8SubriskNot Applicable					
Packing group	II.					
Environmental hazard	Not Applicable					

С	hemwatch: 9-404998				Page <b>9</b> of <b>11</b>	Issue Date: 06/01/2017
Catalogue number: MM-9032			MM-9032	Print Date: 06/01/2017		
V	ersion No: 1.1					
	Special precautions for user		Hazard Label	8		
	Special precautions for user					

# Air transport (ICAO-IATA / DGR)

	-						
UN number	3264						
UN proper shipping name	Corrosive liquid, acidic, inorganic, n.o.s. *						
Transport hazard class(es)	ICAO/IATA Class8ICAO / IATA SubriskNot ApplicableERG Code8L						
Packing group	Ш						
Environmental hazard	Not Applicable						
Special precautions for user	Special provisions         Cargo Only Packing Instructions         Cargo Only Maximum Qty / Pack         Passenger and Cargo Packing Instructions         Passenger and Cargo Maximum Qty / Pack         Passenger and Cargo Limited Quantity Packing Instruction         Passenger and Cargo Limited Maximum Qty / Pack	A3A803       855       30 L       851       1 L       pns     Y840       0.5 L					

# Sea transport (IMDG-Code / GGVSee)

UN number	3264							
UN proper shipping name	CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S.							
Transport hazard class(es)	IMDG Class8IMDG SubriskNot Applicable							
Packing group	Ш							
Environmental hazard	Marine Pollutant							
Special precautions for user	EMS NumberF-A, S-BSpecial provisions274Limited Quantities1 L							

# Transport in bulk according to Annex II of MARPOL and the IBC code

Not Applicable

# SECTION 15 REGULATORY INFORMATION

# Safety, health and environmental regulations / legislation specific for the substance or mixture

Special provisions 386, B2, IB2, T11, TP2, TP27

# NITRIC ACID(7697-37-2) IS FOUND ON THE FOLLOWING REGULATORY LISTS

International Air Transport Association (IATA) Dangerous Goods Regulations - Prohibited List	US - Vermont Permissible Exposure Limits Table Z-1-A Final Rule Limits for Air Contaminants
Passenger and Cargo Aircraft	US - Vermont Permissible Exposure Limits Table Z-1-A Transitional Limits for Air
US - Alaska Limits for Air Contaminants	Contaminants
US - California OEHHA/ARB - Acute Reference Exposure Levels and Target Organs (RELs)	US - Washington Permissible exposure limits of air contaminants
US - California Permissible Exposure Limits for Chemical Contaminants	US - Washington Toxic air pollutants and their ASIL, SQER and de minimis emission values
US - Hawaii Air Contaminant Limits	US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants
US - Idaho - Limits for Air Contaminants	US ACGIH Threshold Limit Values (TLV)
US - Massachusetts - Right To Know Listed Chemicals	US CWA (Clean Water Act) - List of Hazardous Substances
US - Michigan Exposure Limits for Air Contaminants	US EPCRA Section 313 Chemical List
US - Minnesota Permissible Exposure Limits (PELs)	US NIOSH Recommended Exposure Limits (RELs)
US - Oregon Permissible Exposure Limits (Z-1)	US OSHA Permissible Exposure Levels (PELs) - Table Z1
US - Pennsylvania - Hazardous Substance List	US SARA Section 302 Extremely Hazardous Substances
US - Rhode Island Hazardous Substance List	US Toxic Substances Control Act (TSCA) - Chemical Substance Inventory
US - Tennessee Occupational Exposure Limits - Limits For Air Contaminants	
WATER(7732-18-5) IS FOUND ON THE FOLLOWING REGULATORY LISTS	
US - Pennsylvania - Hazardous Substance List	US Toxic Substances Control Act (TSCA) - Chemical Substance Inventory

NICKEL(II) NITRATE(13138-45-9) IS FOUND ON THE FOLLOWING REGULATORY LISTS

Chemwatch: 9-404998	Page 10 of 11 Issue Date: 06/01/2017		
Catalogue number: MM-9032	MM-9032 Print Date: 06/01/2017		
Version No: 1.1			
International Agency for Research on Cancer (IARC) - Agents Classified by the IARC	US - Tennessee Occupational Exposure Limits - Limits For Air Contaminants		
Monographs	US - Vermont Permissible Exposure Limits Table Z-1-A Final Rule Limits for Air Contaminants		
US - Alaska Limits for Air Contaminants	US - Vermont Permissible Exposure Limits Table Z-1-A Transitional Limits for Air		
US - California OEHHA/ARB - Acute Reference Exposure Levels and Target Organs (RELs)	Contaminants		
US - California OEHHA/ARB - Chronic Reference Exposure Levels and Target Organs	US - Washington Permissible exposure limits of air contaminants		
(CRELs)	US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants		
US - California Permissible Exposure Limits for Chemical Contaminants	US ACGIH Threshold Limit Values (TLV)		
US - California Proposition 65 - Carcinogens	US ACGIH Threshold Limit Values (TLV) - Carcinogens		
US - Hawaii Air Contaminant Limits	US Clean Air Act - Hazardous Air Pollutants		
US - Idaho - Limits for Air Contaminants	US CWA (Clean Water Act) - Priority Pollutants		
US - Massachusetts - Right To Know Listed Chemicals	US CWA (Clean Water Act) - Toxic Pollutants		
US - Michigan Exposure Limits for Air Contaminants	US EPCRA Section 313 Chemical List		
US - Minnesota Permissible Exposure Limits (PELs)	US National Toxicology Program (NTP) 14th Report Part A Known to be Human Carcinogens		
US - New Jersey Right to Know - Special Health Hazard Substance List (SHHSL):	US OSHA Permissible Exposure Levels (PELs) - Table Z1		
Carcinogens	US Priority List for the Development of Proposition 65 Safe Harbor Levels - No Significant Risk		
US - Oregon Permissible Exposure Limits (Z-1)	Levels (NSRLs) for Carcinogens and Maximum Allowable Dose Levels (MADLs) for		
US - Pennsylvania - Hazardous Substance List	Chemicals Causing Reproductive Toxicity		
US - Rhode Island Hazardous Substance List	US Toxic Substances Control Act (TSCA) - Chemical Substance Inventory		

### **Federal Regulations**

# Superfund Amendments and Reauthorization Act of 1986 (SARA)

### SECTION 311/312 HAZARD CATEGORIES

Immediate (acute) health hazard	Yes
Delayed (chronic) health hazard	Yes
Fire hazard	No
Pressure hazard	No
Reactivity hazard	No

# US. EPA CERCLA HAZARDOUS SUBSTANCES AND REPORTABLE QUANTITIES (40 CFR 302.4)

Name	Reportable Quantity in Pounds (Ib)	Reportable Quantity in kg
Nitric acid	1000	454
Nickel nitrate	100	45.4

### State Regulations

### US. CALIFORNIA PROPOSITION 65

WARNING: This product contains a chemical known to the State of California to cause cancer and birth defects or other reproductive harm

### US - CALIFORNIA PREPOSITION 65 - CARCINOGENS & REPRODUCTIVE TOXICITY (CRT): LISTED SUBSTANCE

NICKEI COMPOUNDS LISTED	Nickel compounds Listed	
-------------------------	-------------------------	--

National Inventory	Status
Australia - AICS	Υ
Canada - DSL	Y
Canada - NDSL	N (water; nickel(II) nitrate; nitric acid)
China - IECSC	Υ
Europe - EINEC / ELINCS / NLP	Υ
Japan - ENCS	N (water; nickel(II) nitrate; nitric acid)
Korea - KECI	Υ
New Zealand - NZIoC	Υ
Philippines - PICCS	Υ
USA - TSCA	Y
Legend:	Y = All ingredients are on the inventory N = Not determined or one or more ingredients are not on the inventory and are not exempt from listing(see specific ingredients in brackets)

# **SECTION 16 OTHER INFORMATION**

### Other information

# Ingredients with multiple cas numbers

Name	CAS No
nickel(II) nitrate	13138-45-9, 13478-00-7

Classification of the preparation and its individual components has drawn on official and authoritative sources as well as independent review by the Chernwatch Classification committee using available literature references.

The SDS is a Hazard Communication tool and should be used to assist in the Risk Assessment. Many factors determine whether the reported Hazards are Risks in the workplace or other settings. Risks may be determined by reference to Exposures Scenarios. Scale of use, frequency of use and current or available engineering controls must be considered.

Chemwatch: 9-404998	Page 11 of 11	Issue Date: 06/01/2017
Catalogue number: MM-9032	MM-9032	Print Date: 06/01/2017
Version No: 1.1	WW-3032	

PC-TWA: Permissible Concentration-Time Weighted Average PC-STEL: Permissible Concentration-Short Term Exposure Limit IARC: International Agency for Research on Cancer ACGIH: American Conference of Governmental Industrial Hygienists STEL: Short Term Exposure Limit TEEL: Temporary Emergency Exposure Limit。 IDLH: Immediately Dangerous to Life or Health Concentrations OSF: Odour Safety Factor NOAEL :No Observed Adverse Effect Level LOAEL: Lowest Observed Adverse Effect Level TLV: Threshold Limit Value LOD: Limit Of Detection OTV: Odour Threshold Value BCF: BioConcentration Factors BEI: Biological Exposure Index

Apart from any fair dealing for the purposes of private study, research, review or criticism, as permitted under the Copyright Act, no part may be reproduced by any process without written permission from CHEMWATCH. TEL (+61 3) 9572 4700.

