

ICP-MSCS-PE3 Solution B

High-Purity Standards

Catalogue number: ICP-MSCS-PE3_SoIB

Version No: 1.1 Safety Data Sheet according to OSHA HazCom Standard (2012) requirements

Chemwatch Hazard Alert Code: 3 Issue Date: 06/06/2017

Print Date: 06/06/2017 S.GHS.USA.EN

SECTION 1 IDENTIFICATION

Product Identifier

Product name	ICP-MSCS-PE3 Solution B		
Synonyms	CP-MSCS-PE3_SolB		
Proper shipping name	Corrosive liquid, acidic, inorganic, n.o.s.		
Other means of identification	ICP-MSCS-PE3_SolB		

Recommended use of the chemical and restrictions on use

Relevant identified uses Use according to manufacturer's directions.

Name, address, and telephone number of the chemical manufacturer, importer, or other responsible party

Registered company name	High-Purity Standards
Address	PO Box 41727 SC 29423 United States
Telephone	843-767-7900
Fax	843-767-7906
Website	highpuritystandards.com
Email	Not Available

Emergency phone number

Association / Organisation	INFOTRAC
Emergency telephone numbers	1-800-535-5053
Other emergency telephone numbers	1-352-323-3500

SECTION 2 HAZARD(S) IDENTIFICATION

Classification	Serious Eye Damage Category 1, Metal Corrosion Category 1, Skin Corrosion/Irritation Category 1A		
abel elements			
Hazard pictogram(s)			
SIGNAL WORD	DANGER		
lazard statement(s)			
H290	May be corrosive to metals.		
H314	Causes severe skin burns and eye damage.		

Hazard(s) not otherwise specified

Not Applicable

Chemwatch: 9-408048 Page 2 of 10 Issue Date: 06/06/2017 Catalogue number: ICP-MSCS-PE3_SoIB Print Date: 06/06/2017 **ICP-MSCS-PE3 Solution B** Version No: 1.1 P260 Do not breathe dust/fume/gas/mist/vapours/spray. Precautionary statement(s) Response P301+P330+P331 IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. Precautionary statement(s) Storage P405 Store locked up. Precautionary statement(s) Disposal P501 Dispose of contents/container in accordance with local regulations. **SECTION 3 COMPOSITION / INFORMATION ON INGREDIENTS**

Substances

See section below for composition of Mixtures

Mixtures

CAS No	%[weight]	Name
7697-37-2	5	nitric acid
7732-18-5	balance	water
7439-97-6	0.001	mercury (elemental)

SECTION 4 FIRST-AID MEASURES

Description of first aid measures

Eye Contact	 If this product comes in contact with the eyes: Immediately hold eyelids apart and flush the eye continuously with running water. Ensure complete irrigation of the eye by keeping eyelids apart and away from eye and moving the eyelids by occasionally lifting the upper and lower lids. Continue flushing until advised to stop by the Poisons Information Centre or a doctor, or for at least 15 minutes. Transport to hospital or doctor without delay. Removal of contact lenses after an eye injury should only be undertaken by skilled personnel. 			
Skin Contact	 If skin or hair contact occurs: Immediately flush body and clothes with large amounts of water, using safety shower if available. Quickly remove all contaminated clothing, including footwear. Wash skin and hair with running water. Continue flushing with water until advised to stop by the Poisons Information Centre. Transport to hospital, or doctor. 			
Inhalation	 If fumes or combustion products are inhaled remove from contaminated area. Lay patient down. Keep warm and rested. Prostheses such as false teeth, which may block airway, should be removed, where possible, prior to initiating first aid procedures. Apply artificial respiration if not breathing, preferably with a demand valve resuscitator, bag-valve mask device, or pocket mask as trained. Perform CPR if necessary. Transport to hospital, or doctor, without delay. Inhalation of vapours or aerosols (mists, fumes) may cause lung oedema. Corrosive substances may cause lung damage (e.g. lung oedema, fluid in the lungs). As this reaction may be delayed up to 24 hours after exposure, affected individuals need complete rest (preferably in semi-recumbent posture) and must be kept under medical observation even if no symptoms are (vet) manifested. Before any such manifestation, the administration of a spray containing a dexamethasone derivative or beclomethasone derivative may be considered. This must definitely be left to a doctor or person authorised by him/her. (ICSC13719) 			
Ingestion	 For advice, contact a Poisons Information Centre or a doctor at once. Urgent hospital treatment is likely to be needed. If swallowed do NOT induce vomiting. If vomiting occurs, lean patient forward or place on left side (head-down position, if possible) to maintain open airway and prevent aspiration. Observe the patient carefully. Never give liquid to a person showing signs of being sleepy or with reduced awareness; i.e. becoming unconscious. Give water to rinse out mouth, then provide liquid slowly and as much as casualty can comfortably drink. Transport to hospital or doctor without delay. 			

Most important symptoms and effects, both acute and delayed

See Section 11

Indication of any immediate medical attention and special treatment needed

For acute or short term repeated exposures to strong acids:

- Airway problems may arise from laryngeal edema and inhalation exposure. Treat with 100% oxygen initially.
- + Respiratory distress may require cricothyroidotomy if endotracheal intubation is contraindicated by excessive swelling
- Intravenous lines should be established immediately in all cases where there is evidence of circulatory compromise.
- Strong acids produce a coagulation necrosis characterised by formation of a coagulum (eschar) as a result of the dessicating action of the acid on proteins in specific tissues.

INGESTION:
 Immediate dilution (milk or water) within 30 minutes post ingestion is recommended.

- DO NOT attempt to neutralise the acid since exothermic reaction may extend the corrosive injury.
- Be careful to avoid further vomit since re-exposure of the mucosa to the acid is harmful. Limit fluids to one or two glasses in an adult.
- Charcoal has no place in acid management.
- Some authors suggest the use of lavage within 1 hour of ingestion.

SKIN:

MSCS-PE3 Solution B	Print Date: 06/06/2017
	-MSCS-PE3 Solution B

• Skin lesions require copious saline irrigation. Treat chemical burns as thermal burns with non-adherent gauze and wrapping.

Deep second-degree burns may benefit from topical silver sulfadiazine.

EYE:

Eye injuries require retraction of the eyelids to ensure thorough irrigation of the conjuctival cul-de-sacs. Irrigation should last at least 20-30 minutes. DO NOT use neutralising agents or any other additives. Several litres of saline are required.

Cycloplegic drops, (1% cyclopentolate for short-term use or 5% homatropine for longer term use) antibiotic drops, vasoconstrictive agents or artificial tears may be indicated dependent on the severity of the injury.

Steroid eye drops should only be administered with the approval of a consulting ophthalmologist).

[Ellenhorn and Barceloux: Medical Toxicology]

SECTION 5 FIRE-FIGHTING MEASURES

Extinguishing media

- There is no restriction on the type of extinguisher which may be used.
- Use extinguishing media suitable for surrounding area.

Special hazards arising from the substrate or mixture

Fire Incompatibility None known.

Special protective equipment and precautions for fire-fighters

Fire Fighting	
Fire/Explosion Hazard	 Non combustible. Not considered to be a significant fire risk. Acids may react with metals to produce hydrogen, a highly flammable and explosive gas. Heating may cause expansion or decomposition leading to violent rupture of containers. May emit corrosive, poisonous fumes. May emit acrid smoke.

SECTION 6 ACCIDENTAL RELEASE MEASURES

Personal precautions, protective equipment and emergency procedures

See section 8

Environmental precautions

See section 12

Methods and material for containment and cleaning up

Minor Spills	 Drains for storage or use areas should have retention basins for pH adjustments and dilution of spills before discharge or disposal of material. Check regularly for spills and leaks. Clean up all spills immediately. Avoid breathing vapours and contact with skin and eyes. Control personal contact with the substance, by using protective equipment. Contain and absorb spill with sand, earth, inert material or vermiculite. Wipe up. Place in a suitable, labelled container for waste disposal.
Major Spills	#

Personal Protective Equipment advice is contained in Section 8 of the SDS.

SECTION 7 HANDLING AND STORAGE

Precautions for safe handling

Safe handling	 Avoid all personal contact, including inhalation. Wear protective clothing when risk of exposure occurs. Use in a well-ventilated area. WARNING: To avoid violent reaction, ALWAYS add material to water and NEVER water to material. Avoid smoking, naked lights or ignition sources. Avoid contact with incompatible materials. When handling, DO NOT eat, drink or smoke. Keep containers securely sealed when not in use. Avoid physical damage to containers. Always wash hands with soap and water after handling. Work clothes should be laundered separately. Launder contaminated clothing before re-use. Use good occupational work practice. Observe manufacturer's storage and handling recommendations contained within this SDS. Atmosphere should be regularly checked against established exposure standards to ensure safe working conditions are maintained.
Other information	 Store in original containers. Keep containers securely sealed. Store in a cool, dry, well-ventilated area. Store away from incompatible materials and foodstuff containers. Protect containers against physical damage and check regularly for leaks. Observe manufacturer's storage and handling recommendations contained within this SDS.

Conditions for safe storage, including any incompatibilities

Suitable container	DO NOT use aluminium or galvanised containers
--------------------	---

Chemwatch: 9-408048 Catalogue number: ICP-MSCS-PE3_SoIB		Page 4 of 10	Issue Date: 06/06/2017
		ICP-MSCS-PE3 Solution B	Print Date: 06/06/2017
	For materials with a viscosity of at least 26 Removable head packaging; Cans with friction closures and low pressure tubes and cartridges may be used. - Where combination packages are used, an	ed and free from leaks.	
Storage incompatibility	 Inorganic acids neutralise chemical b amounts of heat in small spaces. The dissolution of inorganic acids in v The addition of water to inorganic acid resulting "bumping" can spatter the a Inorganic acids react with active meta Inorganic acids react with cyanide cor Inorganic acids generate flammable a 	Is, including such structural metals as aluminum and iron, to release hyderisation of certain classes of organic compounds. npounds to release gaseous hydrogen cyanide. Ind/or toxic gases in contact with dithiocarbamates, isocyanates, mercap rating reactions occur with sulfites, nitrites, thiosulfates (to give H2S and	tralisation can generate dangerously large may generate significant heat. orne of the water to boil explosively. The drogen, a flammable gas. otans, nitrides, nitriles, sulfides, and strong

SECTION 8 EXPOSURE CONTROLS / PERSONAL PROTECTION

Control parameters

OCCUPATIONAL EXPOSURE LIMITS (OEL)

INGREDIENT DATA

Source	Ingredient	Material name		TWA	STEL	Peak	Notes
US OSHA Permissible Exposure Levels (PELs) - Table Z1	nitric acid	Nitric acid		5 mg/m3 / 2 ppm	10 mg/m3 / 4 ppm	Not Available	TLV® Basis: URT & eye irr; dental erosion
US NIOSH Recommended Exposure Limits (RELs)	nitric acid		acid, Hydrogen nitrate, Red NA), White fuming nitric acid	5 mg/m3 / 2 ppm	4 ppm	Not Available	Not Available
US ACGIH Threshold Limit Values (TLV)	nitric acid	Nitric acid		2 ppm	Not Available	Not Available	Not Available
US OSHA Permissible Exposure Levels (PELs) - Table Z1	mercury (elemental)	Mercury (vapor)	Mercury (vapor)		Not Available	0.1 mg/m3	See Table Z-2;(as Hg)
US OSHA Permissible Exposure Levels (PELs) - Table Z2	mercury (elemental)	Mercury	Mercury		Not Available	Other:0.1 mg/m3	(Z37.8–1971)
US NIOSH Recommended Exposure Limits (RELs)	mercury (elemental)	Mercury metal: Colloidal mercury, Metallic mercury, Quicksilver		Not Available	Not Available	Not Available	Not Available
EMERGENCY LIMITS							
Ingredient	Material name		TEEL-1	TEEL-2		TEE	L-3

Ingredient	Material name	TEEL-1	TEEL-2	TEEL-3	
nitric acid	Nitric acid	Not Available	Not Available	Not Available	
mercury (elemental)	Mercury vapor	0.15 mg/m3	Not Available	Not Available	
Ingredient	Original IDLH		Revised IDLH		
nitric acid	100 ppm		25 ppm		
water	Not Available		Not Available		
mercury (elemental)	10 mg/m3 / 28 mg/m3	10 mg/m3 / 28 mg/m3			

Exposure controls

Appropriate engineering	Engineering controls are used to remove a hazard or place a barrier between the worker and the hazard. Well-designed engineering controls can be highly effective in protecting workers and will typically be independent of worker interactions to provide this high level of protection. The basic types of engineering controls are: Process controls which involve changing the way a job activity or process is done to reduce the risk. Enclosure and/or isolation of emission source which keeps a selected hazard "physically" away from the worker and ventilation that strategically "adds" and "removes" air in the work environment. Ventilation can remove or dilute an air contaminant if designed property. The design of a ventilation system must match
controls	the particular process and chemical or contaminant in use. Employers may need to use multiple types of controls to prevent employee overexposure.
	Local exhaust ventilation usually required. If risk of overexposure exists, wear approved respirator. Correct fit is essential to obtain adequate protection.

Page 5 of 10

ICP-MSCS-PE3 Solution B

	An approved self contained breathing apparatus (SCBA) may be required in some situations. Provide adequate ventilation in warehouse or closed storage area. Air contaminants generated in the turn, determine the "capture velocities" of fresh circulating air required to effectively remove the conta		pe" velocities which, in			
	Type of Contaminant:		Air Speed:			
	solvent, vapours, degreasing etc., evaporating from tank (in still air).	0.25-0.5 m/s (50-100 f/min.)				
	aerosols, fumes from pouring operations, intermittent container filling, low speed conveyer transfers, welding, spray drift, plating acid fumes, pickling (released at low velocity into zone of active generation)					
	direct spray, spray painting in shallow booths, drum filling, conveyer loading, crusher dusts, gas dis zone of rapid air motion)	scharge (active generation into	1-2.5 m/s (200-500 f/min.)			
	grinding, abrasive blasting, tumbling, high speed wheel generated dusts (released at high initial ve air motion).	locity into zone of very high rapid	2.5-10 m/s (500-2000 f/min.)			
	Within each range the appropriate value depends on:		·			
	Lower end of the range	Upper end of the range				
	1: Room air currents minimal or favourable to capture	1: Disturbing room air currents				
	2: Contaminants of low toxicity or of nuisance value only.	2: Contaminants of high toxicity				
	3: Intermittent, low production.	3: High production, heavy use				
	4: Large hood or large air mass in motion	4: Small hood-local control only				
	of distance from the extraction point (in simple cases). Therefore the air speed at the extraction point distance from the contaminating source. The air velocity at the extraction fan, for example, should be solvents generated in a tank 2 meters distant from the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when	should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/m ons, producing performance deficit	nin) for extraction of is within the extraction			
Personal protection	distance from the contaminating source. The air velocity at the extraction fan, for example, should be a solvents generated in a tank 2 meters distant from the extraction point. Other mechanical consideration	should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/m ons, producing performance deficit	Ifter reference to hin) for extraction of is within the extraction			
Personal protection	distance from the contaminating source. The air velocity at the extraction fan, for example, should be a solvents generated in a tank 2 meters distant from the extraction point. Other mechanical consideration	should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/m ons, producing performance deficit extraction systems are installed of desirable, as in laboratories; specta a danger of splashing, or if the ma goggles must be properly fitted. protection of eyes; these afford fac ants. A written policy document, de a review of lens absorption and ac trained in their removal and suitab	Inter reference to hin) for extraction of is within the extraction r used. Access are not sufficient terial may be under e protection. Accession of the class of le equipment should be e. Lens should be removed			
	 distance from the contaminating source. The air velocity at the extraction fan, for example, should be a solvents generated in a tank 2 meters distant from the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration is needed such as when handling bulk-quantities, where there is pressure. Chemical goggles whenever there is a danger of the material coming in contact with the eyes; goes a special hazard; soft contact lenses may absorb and concentrate intit lenses or restrictions on use, should be created for each workplace or task. This should include a chemicals in use and an account of injury experience. Medical and first-aid personnel should be readily available. In the event of chemical exposure, begin eye irrigation immediately and remove at the first signs of eye redness or irritation - lens should be removed in a clean environment only 	should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/m ons, producing performance deficit extraction systems are installed of desirable, as in laboratories; specta a danger of splashing, or if the ma goggles must be properly fitted. protection of eyes; these afford fac ants. A written policy document, de a review of lens absorption and ac trained in their removal and suitab	Inter reference to hin) for extraction of is within the extraction r used. Access are not sufficient terial may be under e protection. Accession of the class of le equipment should be e. Lens should be removed			
Eye and face protection	 distance from the contaminating source. The air velocity at the extraction fan, for example, should be a solvents generated in a tank 2 meters distant from the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration is needed such as when handling bulk-quantities, where there is pressure. Chemical goggles.whenever there is a danger of the material coming in contact with the eyes; or the shield (20 cm, 8 in minimum) may be required for supplementary but never for primary is Alternatively a gas mask may replace splash goggles and face shields. Contact lenses may pose a special hazard; soft contact lenses may absorb and concentrate intil lenses or restrictions on use, should be created for each workplace or task. This should include is chemicals in use and an account of injury experience. Medical and first-aid personnel should be readily available. In the event of chemical exposure, begin eye irrigation immediately and remove at the first signs of eye redness or irritation - lens should be removed in a clean environment only Current Intelligence Bulletin 59], [AS/NZS 1336 or national equivalent] 	should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/m ons, producing performance deficit extraction systems are installed of desirable, as in laboratories; specta a danger of splashing, or if the ma goggles must be properly fitted. protection of eyes; these afford fac ants. A written policy document, de a review of lens absorption and ac trained in their removal and suitab contact lens as soon as practicabl after workers have washed hands	Inter reference to hin) for extraction of is within the extraction r used. Access are not sufficient terial may be under e protection. Accession of the class of le equipment should be e. Lens should be removed			
Eye and face protection	 distance from the contaminating source. The air velocity at the extraction fan, for example, should be a solvents generated in a tank 2 meters distant from the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration is needed such as when handling bulk-quantities, where there is pressure. Chemical goggles.whenever there is a danger of the material coming in contact with the eyes; or Full face shield (20 cm, 8 in minimum) may be required for supplementary but never for primary is Alternatively a gas mask may replace splash goggles and face shields. Contact lenses may pose a special hazard; soft contact lenses may absorb and concentrate irrit lenses or restrictions on use, should be created for each workplace or task. This should include chemicals in use and an account of injury experience. Medical and first-aid personnel should be readily available. In the event of chemical exposure, begin eye irrigation immediately and remove at the first signs of eye redness or irritation - lens should be removed in a clean environment only Current Intelligence Bulletin 59], [AS/NZS 1336 or national equivalent] See Hand protection below Elbow length PVC gloves 	should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/m ons, producing performance deficit extraction systems are installed of desirable, as in laboratories; specta a danger of splashing, or if the ma goggles must be properly fitted. protection of eyes; these afford fac ants. A written policy document, de a review of lens absorption and ac trained in their removal and suitab contact lens as soon as practicabl after workers have washed hands	Inter reference to hin) for extraction of is within the extraction r used. Access are not sufficient terial may be under e protection. Accession of the class of le equipment should be e. Lens should be removed			
Eye and face protection Skin protection Hands/feet protection	 distance from the contaminating source. The air velocity at the extraction fan, for example, should be a solvents generated in a tank 2 meters distant from the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when the extraction point. Other mechanical consideration apparent to the extraction point. Other mechanical consideration is needed such as when handling bulk-quantities, where there is pressure. Chemical goggles whenever there is a danger of the material coming in contact with the eyes; or a full face shield (20 cm, 8 in minimum) may be required for supplementary but never for primary is a lateratively a gas mask may replace splash goggles and face shields. Contact lenses may pose a special hazard; soft contact lenses may absorb and concentrate irritil lenses or restrictions on use, should be created for each workplace or task. This should include chemicals in use and an account of injury experience. Medical and first-aid personnel should be readily available. In the event of chemical exposure, begin eye irrigation immediately and remove at the first signs of eye redness or irritation - lens should be removed in a clean environment only Current Intelligence Bulletin 59], [AS/NZS 1336 or national equivalent] See Hand protection below Elbow length PVC gloves When handling corrosive liquids, wear trousers or overalls outside of boots, to avoid spills enterting on the subspills enterting	should be adjusted, accordingly, a a minimum of 1-2 m/s (200-400 f/m ons, producing performance deficit extraction systems are installed of desirable, as in laboratories; specta a danger of splashing, or if the ma goggles must be properly fitted. protection of eyes; these afford fac ants. A written policy document, de a review of lens absorption and ac trained in their removal and suitab contact lens as soon as practicabl after workers have washed hands	Inter reference to hin) for extraction of is within the extraction r used. Access are not sufficient terial may be under e protection. Accession of the class of le equipment should be e. Lens should be removed			

Respiratory protection

Type A Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

SECTION 9 PHYSICAL AND CHEMICAL PROPERTIES

Information on basic physical and chemical properties

Appearance	Not Available		
Physical state	Liquid	Relative density (Water = 1)	Not Available
Odour	Not Available	Partition coefficient n-octanol / water	Not Available
Odour threshold	Not Available	Auto-ignition temperature (°C)	Not Available
pH (as supplied)	Not Available	Decomposition temperature	Not Available
Melting point / freezing point (°C)	Not Available	Viscosity (cSt)	Not Available
Initial boiling point and boiling range (°C)	Not Available	Molecular weight (g/mol)	Not Available

riasii politi (C)	Not Available	Taste	NULAVAIIADIE
Evaporation rate	Not Available	Explosive properties	Not Available
Flammability	Not Available	Oxidising properties	Not Available
Upper Explosive Limit (%)	Not Available	Surface Tension (dyn/cm or mN/m)	Not Available
Lower Explosive Limit (%)	Not Available	Volatile Component (%vol)	Not Available
Vapour pressure (kPa)	Not Available	Gas group	Not Available
Solubility in water (g/L)	Miscible	pH as a solution (1%)	Not Available
Vapour density (Air = 1)	Not Available	VOC g/L	Not Available

SECTION 10 STABILITY AND REACTIVITY

Reactivity	See section 7
Chemical stability	Contact with alkaline material liberates heat
Possibility of hazardous reactions	See section 7
Conditions to avoid	See section 7
Incompatible materials	See section 7
Hazardous decomposition products	See section 5

SECTION 11 TOXICOLOGICAL INFORMATION

Information on toxicological effects

Inhaled	The material can cause respiratory irritation in some persons. The body's response to such irritation can cause further lung damage. Corrosive acids can cause irritation of the respiratory tract, with coughing, choking and mucous membrane damage. There may be dizziness, headache, nausea and weakness. The material has NOT been classified by EC Directives or other classification systems as "harmful by inhalation". This is because of the lack of corroborating animal or human evidence.						
Ingestion	Ingestion of acidic corrosives may produce burns around and in the mouth, the throat and oesophagus. Immediate pain and difficulties in swallowing and speaking may also be evident. The material has NOT been classified by EC Directives or other classification systems as "harmful by ingestion". This is because of the lack of corroborating animal or human evidence.						
Skin Contact	Skin contact with acidic corrosives may result in pain and burns; these may be deep with distinct edges and may heal slowly with the formation of scar tissue. Skin contact is not thought to have harmful health effects (as classified under EC Directives); the material may still produce health damage following entry through wounds, lesions or abrasions. Open cuts, abraded or irritated skin should not be exposed to this material Entry into the blood-stream, through, for example, cuts, abrasions or lesions, may produce systemic injury with harmful effects. Examine the skin prior to the use of the material and ensure that any external damage is suitably protected.						
Eye	If applied to the eyes, this material causes severe eye damage. Direct eye contact with acid corrosives may produce pain, tears, sensitivity to lig completely.	ght and burns. Mild burns of tl	ne epithelia generally recover rapidly and				
Chronic	Repeated or prolonged exposure to acids may result in the erosion of teeth, swelling and/or ulceration of mouth lining. Irritation of airways to lung, with cough, and inflammation of lung tissue often occurs. Long-term exposure to respiratory irritants may result in airways disease, involving difficulty breathing and related whole-body problems. Substance accumulation, in the human body, may occur and may cause some concern following repeated or long-term occupational exposure.						
ICP-MSCS-PE3 Solution B	TOXICITY	IRRITATION					
	Not Available	Not Available					
nitric acid	TOXICITY		IRRITATION				
	Inhalation (rat) LC50: 625 ppm/1h*t ^[2]		Not Available				
water	TOXICITY	IRRITATION					
Hator	Not Available Not Available						
mercury (elemental)	TOXICITY		IRRITATION				
	Oral (rat) LD50: >9.2 mg/kg ^[1]		Not Available				
Legend:	1. Value obtained from Europe ECHA Registered Substances - Acute toxicity 2.	* Value obtained from monut	acturar's SDS Unless otherwise specified data				
Legena:	extracted from RTECS - Register of Toxic Effect of chemical Substances	value obtained north Mahul					
NITRIC ACID	For acid mists, aerosols, vapours Test results suggest that eukaryotic cells are susceptible to genetic damage wh The material may produce severe irritation to the eye causing pronounced inflan The material may produce respiratory tract irritation, and result in damage to th	nmation.	g function.				

Page 7 of 10

ICP-MSCS-PE3 Solution B

	The material may cause severe skin irritation after prolonged or repeated exposure and may produce on contact skin redness, swelling, the production of vesicles, scaling and thickening of the skin. Oral (?) LD50: 50-500 mg/kg * [Various Manufacturers]				
WATER	No significant acute toxicological data identified in literature	search.			
MERCURY (ELEMENTAL)	Animal studies have shown that mercury may be a reproductiv	e effector.			
NITRIC ACID & MERCURY (ELEMENTAL)	Asthma-like symptoms may continue for months or even years after exposure to the material ends.				
A	8	0	8		
Acute Toxicity	\otimes	Carcinogenicity	\otimes		
Skin Irritation/Corrosion	×	Reproductivity	\otimes		
Serious Eye Damage/Irritation	✓	STOT - Single Exposure	0		
Respiratory or Skin sensitisation	0	STOT - Repeated Exposure	0		
Mutagenicity	0	Aspiration Hazard	0		
		Legend: 🗙	– Data available but does not fill the criteria for classification		

Data available to make classification

🚫 – Data Not Available to make classification

SECTION 12 ECOLOGICAL INFORMATION

	ENDPOINT		TEST DURATION (HR)		SPECIES	6	VALUE	E	SO	URCE
CP-MSCS-PE3 Solution B	Not Applicable		Not Applicable		Not Appli	cable	Not Ap	plicable	Not	Applicable
	ENDPOINT		TEST DURATION (HR)			SPECIES		VALUE	5	SOURCE
nitric acid	NOEC		16			Crustacea		107mg/L	4	1
water	ENDPOINT Not Applicable		TEST DURATION (HR) Not Applicable		SPECIES Not Appli		VALUE Not Ap	plicable		URCE Applicable
	ENDPOINT	TE	ST DURATION (HR)	SPEC	IFS			VALUE		SOURCE
	LC50	96		Fish	120			0.004mg/L		4
	EC50	48		Crusta	acea			0.0035mg/L	_	5
mercury (elemental)	EC50	72		Algae	or other aq	uatic plants		0.0025mg/L	-	4
	BCF	720		Fish				0.001mg/L		4
	EC50	240		Fish				0.0003mg/L	-	5
	NOEC	268	88 Crustacea		a		0.00025mg	/L	2	

Legend:

Extracted from 1. IUCLID Toxicity Data 2. Europe ECHA Registered Substances - Ecotoxicological Information - Aquatic Toxicity 3. EPIWIN Suite V3.12 (QSAR) - Aquatic Toxicity Data (Estimated) 4. US EPA, Ecotox database - Aquatic Toxicity Data 5. ECETOC Aquatic Hazard Assessment Data 6. NITE (Japan) - Bioconcentration Data 7. METI (Japan) - Bioconcentration Data 8. Vendor Data

Ecotoxicity:

The tolerance of water organisms towards pH margin and variation is diverse. Recommended pH values for test species listed in OECD guidelines are between 6.0 and almost 9. Acute testing with fish showed 96h-LC50 at about pH 3.5

Prevent, by any means available, spillage from entering drains or water courses.

DO NOT discharge into sewer or waterways.

Persistence and degradability

Ingredient	Persistence: Water/Soil	Persistence: Air
water	LOW	LOW

Bioaccumulative potential

Ingredient	Bioaccumulation
water	LOW (LogKOW = -1.38)

Mobility in soil

Mobility III 301	
Ingredient	Mobility
water	LOW (KOC = 14.3)

Chemwatch: 9-408048	Page 8 of 10	Issue Date: 06/06/2017
Catalogue number: ICP-MSCS-PE3_SoIB	ICP-MSCS-PE3 Solution B	Print Date: 06/06/2017
Version No: 1.1		
Waste treatment methods		
b. De suele unit ensure a se si bla		

	Recycle wherever possible.
	Consult manufacturer for recycling options or consult local or regional waste management authority for disposal if no suitable treatment or disposal facility
	can be identified.
Product / Packaging	Treat and neutralise at an approved treatment plant. Treatment should involve: Neutralisation with soda-ash or soda-lime followed by: burial in a land-fill
disposal	specifically licensed to accept chemical and / or pharmaceutical wastes or Incineration in a licensed apparatus (after admixture with suitable combustible
	material).
	Decontaminate empty containers with 5% aqueous sodium hydroxide or soda ash, followed by water. Observe all label safeguards until containers are
	cleaned and destroyed.

SECTION 14 TRANSPORT INFORMATION

Labels Required



Land transport (DOT)

UN number	3264
UN humber	3204
UN proper shipping name	Corrosive liquid, acidic, inorganic, n.o.s.
Transport hazard class(es)	Class8SubriskNot Applicable
Packing group	II
Environmental hazard	Not Applicable
Special precautions for user	Hazard Label8Special provisions386, B2, IB2, T11, TP2, TP27

Air transport (ICAO-IATA / DGR)

Sea transport (IMDG-Code / GGVSee)

UN number	264		
UN proper shipping name	ORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S.		
Transport hazard class(es)	IMDG Class8IMDG SubriskNot Applicable		
Packing group	II		
Environmental hazard	Not Applicable		
Special precautions for user	EMS NumberF-A, S-BSpecial provisions274		

Continued...

Pollution Category Y; Y	Print Date: 06/06/20 Ship Type 2 2	
Pollution Category Y; Y		
Y; Y		
Y; Y		
Y; Y		
Y; Y		
	2 2	
cture		
ture		
	Dula Limita fan Air Oantaminanta	
hissible Exposure Limits Table Z-1-A Final F		
hissible Exposure Limits Table Z-1-A Transi	itional Limits for Air	
armianible overagura limits of air contoming	nto	
ermissible exposure limits of air contaminar		
oxic air pollutants and their ASIL, SQER and		
US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants		
US ACGIH Threshold Limit Values (TLV)		
US CWA (Clean Water Act) - List of Hazardous Substances		
US EPCRA Section 313 Chemical List US NIOSH Recommended Exposure Limits (RELs)		
,		
US OSHA Permissible Exposure Levels (PELs) - Table Z1		
US SARA Section 302 Extremely Hazardous Substances US Toxic Substances Control Act (TSCA) - Chemical Substance Inventory		
es Control Act (ISCA) - Chemical Substanc	ce inventory	
es Control Act (TSCA) - Chemical Substand	ce Inventory	
ermissible exposure limits of air contaminar	nts	
oxic air pollutants and their ASIL, SQER and		
c and Hazardous Substances Table Z1 Lim		
c and Hazardous Substances Table Z-2 Ac		
m peak above the acceptable ceiling conce		
old Limit Values (TLV)		
US ACGIH Threshold Limit Values (TLV) - Carcinogens		
I Risk Levels for Hazardous Substances (N	MRLs)	
US Clean Air Act - Hazardous Air Pollutants		
US CWA (Clean Water Act) - Priority Pollutants		
US CWA (Clean Water Act) - Toxic Pollutants		
US EPA Carcinogens Listing		
1 313 Chemical List		
US NIOSH Recommended Exposure Limits (RELs)		
US OSHA Permissible Exposure Levels (PELs) - Table Z1		
ble Exposure Levels (PELs) - Table Z2		
he Development of Proposition 65 Safe Ha	arbor Levels - No Significant Risl	
	se Levels (MADLs) for	
Reproductive Toxicity		
imum Allowable Concentrations (SMACs) f		
on nr ssi ssi r ti or	on 313 Chemical List nmended Exposure Limits (RELs)	

Superfund Amendments and Reauthorization Act of 1986 (SARA)

SECTION 311/312 HAZARD CATEGORIES

Immediate (acute) health hazard	Yes
Delayed (chronic) health hazard	No
Fire hazard	No
Pressure hazard	No
Reactivity hazard	No

US. EPA CERCLA HAZARDOUS SUBSTANCES AND REPORTABLE QUANTITIES (40 CFR 302.4)

Name	Reportable Quantity in Pounds (Ib)	Reportable Quantity in kg
Nitric acid	1000	454
Mercury	1	0.454

State Regulations

US. CALIFORNIA PROPOSITION 65

Chemwatch: 9-408048	Page 10 of 10	Issue Date: 06/06/2017
Catalogue number: ICP-MSCS-PE3_SoIB	ICP-MSCS-PE3 Solution B	Print Date: 06/06/2017
Version No: 1.1		

WARNING: This product contains a chemical known to the State of California to cause cancer and birth defects or other reproductive harm

US - CALIFORNIA PREPOSITION 65 - CARCINOGENS & REPRODUCTIVE TOXICITY (CRT): LISTED SUBSTANCE

Mercury and mercury compounds Listed

National Inventory	Status
Australia - AICS	Y
Canada - DSL	Y
Canada - NDSL	N (water; mercury (elemental); nitric acid)
China - IECSC	Y
Europe - EINEC / ELINCS / NLP	Y
Japan - ENCS	N (water; mercury (elemental); nitric acid)
Korea - KECI	Y
New Zealand - NZIoC	Y
Philippines - PICCS	Y
USA - TSCA	Y
Legend:	Y = All ingredients are on the inventory N = Not determined or one or more ingredients are not on the inventory and are not exempt from listing(see specific ingredients in brackets)

SECTION 16 OTHER INFORMATION

Other information

Classification of the preparation and its individual components has drawn on official and authoritative sources as well as independent review by the Chemwatch Classification committee using available literature references.

The SDS is a Hazard Communication tool and should be used to assist in the Risk Assessment. Many factors determine whether the reported Hazards are Risks in the workplace or other settings. Risks may be determined by reference to Exposures Scenarios. Scale of use, frequency of use and current or available engineering controls must be considered.

Definitions and abbreviations

PC – TWA: Permissible Concentration-Time Weighted Average PC – STEL: Permissible Concentration-Short Term Exposure Limit IARC: International Agency for Research on Cancer ACGIH: American Conference of Governmental Industrial Hygienists STEL: Short Term Exposure Limit TEEL: Temporary Emergency Exposure Limit. IDLH: Immediately Dangerous to Life or Health Concentrations OSF: Odour Safety Factor NOAEL: No Observed Adverse Effect Level LOAEL: Lowest Observed Adverse Effect Level LOAEL: Lowest Observed Adverse Effect Level TLV: Threshold Limit Value LOD: Limit of Detection OTV: Odour Threshold Value BCF: BioConcentration Factors BEI: Biological Exposure Index

This document is copyright.

Apart from any fair dealing for the purposes of private study, research, review or criticism, as permitted under the Copyright Act, no part may be reproduced by any process without written permission from CHEMWATCH. TEL (+61 3) 9572 4700.