

CLP Spike Standard 2

High-Purity Standards

Catalogue number: CLP-SP-2

Version No: 1.1 Safety Data Sheet according to OSHA HazCom Standard (2012) requirements

Chemwatch Hazard Alert Code: 3 Issue Date: 06/03/2017

Print Date: 06/03/2017 S.GHS.USA.EN

SECTION 1 IDENTIFICATION

Product Identifier

Product name	CLP Spike Standard 2
Synonyms	CLP-SP-2
Proper shipping name	Corrosive liquid, acidic, inorganic, n.o.s.
Other means of identification	CLP-SP-2

Recommended use of the chemical and restrictions on use

Relevant identified uses Use according to manufacturer's directions.

Name, address, and telephone number of the chemical manufacturer, importer, or other responsible party

Registered company name	High-Purity Standards
Address	PO Box 41727 SC 29423 United States
Telephone	843-767-7900
Fax	843-767-7906
Website	highpuritystandards.com
Email	Not Available

Emergency phone number

Association / Organisation	INFOTRAC
Emergency telephone numbers	1-800-535-5053
Other emergency telephone numbers	1-352-323-3500

SECTION 2 HAZARD(S) IDENTIFICATION

Classification	Metal Corrosion Category 1, Skin Corrosion/Irritation Category 1A, Serious Eye Damage Category 1
abel elements	
Hazard pictogram(s)	
SIGNAL WORD	DANGER
lazard statement(s)	
H290	May be corrosive to metals.
H314	Causes severe skin burns and eye damage.

Hazard(s) not otherwise specified

Not Applicable

Chemwatch: 9-405982

Page 2 of 10 CLP Spike Standard 2

Catalogue number: CLP-SP-2 Version No: 1.1

P260	Do not breathe dust/fume/gas/mist/vapours/spray.
Precautionary statement(s)	Response
P301+P330+P331	IF SWALLOWED: Rinse mouth. Do NOT induce vomiting.
Precautionary statement(s)	Storage
P405	Store locked up.
Precautionary statement(s)) Disposal
P501	Dispose of contents/container in accordance with local regulations.

Substances

See section below for composition of Mixtures

Mixtures

CAS No	%[weight]	Name
7697-37-2	2	nitric acid
7732-18-5	balance	water
7440-36-0	0.05	antimony
87-69-4	5	tartaric acid

SECTION 4 FIRST-AID MEASURES

Description of first aid measures

Eye Contact	 If this product comes in contact with the eyes: Immediately hold eyelids apart and flush the eye continuously with running water. Ensure complete irrigation of the eye by keeping eyelids apart and away from eye and moving the eyelids by occasionally lifting the upper and lower lids. Continue flushing until advised to stop by the Poisons Information Centre or a doctor, or for at least 15 minutes. Transport to hospital or doctor without delay. Removal of contact lenses after an eye injury should only be undertaken by skilled personnel.
Skin Contact	 If skin or hair contact occurs: Immediately flush body and clothes with large amounts of water, using safety shower if available. Quickly remove all contaminated clothing, including footwear. Wash skin and hair with running water. Continue flushing with water until advised to stop by the Poisons Information Centre. Transport to hospital, or doctor.
Inhalation	 If fumes or combustion products are inhaled remove from contaminated area. Lay patient down. Keep warm and rested. Prostheses such as false teeth, which may block airway, should be removed, where possible, prior to initiating first aid procedures. Apply artificial respiration if not breathing, preferably with a demand valve resuscitator, bag-valve mask device, or pocket mask as trained. Perform CPR if necessary. Transport to hospital, or doctor, without delay. Inhalation of vapours or aerosols (mists, fumes) may cause lung oedema. Corrosive substances may cause lung damage (e.g. lung oedema, fluid in the lungs). As this reaction may be delayed up to 24 hours after exposure, affected individuals need complete rest (preferably in semi-recumbent posture) and must be kept under medical observation, the administration of a spray containing a dexamethasone derivative or beclomethasone derivative may be considered. This must definitely be left to a doctor or person authorised by him/her. (ICSC13719)
Ingestion	 For advice, contact a Poisons Information Centre or a doctor at once. Urgent hospital treatment is likely to be needed. If swallowed do NOT induce vomiting. If vomiting occurs, lean patient forward or place on left side (head-down position, if possible) to maintain open airway and prevent aspiration. Observe the patient carefully. Never give liquid to a person showing signs of being sleepy or with reduced awareness; i.e. becoming unconscious. Give water to rinse out mouth, then provide liquid slowly and as much as casuality can comfortably drink. Transport to hospital or doctor without delay.

Most important symptoms and effects, both acute and delayed

See Section 11

Indication of any immediate medical attention and special treatment needed

For acute or short term repeated exposures to strong acids:

- Airway problems may arise from laryngeal edema and inhalation exposure. Treat with 100% oxygen initially.
- ▶ Respiratory distress may require cricothyroidotomy if endotracheal intubation is contraindicated by excessive swelling
- Intravenous lines should be established immediately in all cases where there is evidence of circulatory compromise.
- + Strong acids produce a coagulation necrosis characterised by formation of a coagulum (eschar) as a result of the dessicating action of the acid on proteins in specific tissues.

INGESTION:

- Immediate dilution (milk or water) within 30 minutes post ingestion is recommended.
- DO NOT attempt to neutralise the acid since exothermic reaction may extend the corrosive injury.
- Be careful to avoid further vomit since re-exposure of the mucosa to the acid is harmful. Limit fluids to one or two glasses in an adult.
- · Charcoal has no place in acid management.

Chemwatch: 9-405982
Catalogue number: CLP-SP-2

Version No: 1.1

CLP Spike Standard 2

- Some authors suggest the use of lavage within 1 hour of ingestion.
- SKIN:
 - Skin lesions require copious saline irrigation. Treat chemical burns as thermal burns with non-adherent gauze and wrapping.
- Deep second-degree burns may benefit from topical silver sulfadiazine.

EYE:

- Eye injuries require retraction of the eyelids to ensure thorough irrigation of the conjuctival cul-de-sacs. Irrigation should last at least 20-30 minutes. DO NOT use neutralising agents or any other additives. Several litres of saline are required.
- Cycloplegic drops, (1% cyclopentolate for short-term use or 5% homatropine for longer term use) antibiotic drops, vasoconstrictive agents or artificial tears may be indicated dependent on the severity of the injury.
- Steroid eye drops should only be administered with the approval of a consulting ophthalmologist).

[Ellenhorn and Barceloux: Medical Toxicology]

SECTION 5 FIRE-FIGHTING MEASURES

Extinguishing media

- There is no restriction on the type of extinguisher which may be used.
- Use extinguishing media suitable for surrounding area.

Special hazards arising from the substrate or mixture

Fire Incompatibility None known.

Special protective equipment and precautions for fire-fighters

Fire Fighting	
Fire/Explosion Hazard	 Non combustible. Not considered to be a significant fire risk. Acids may react with metals to produce hydrogen, a highly flammable and explosive gas. Heating may cause expansion or decomposition leading to violent rupture of containers. May emit corrosive, poisonous fumes. May emit acrid smoke.

SECTION 6 ACCIDENTAL RELEASE MEASURES

Personal precautions, protective equipment and emergency procedures

See section 8

Environmental precautions

See section 12

Methods and material for containment and cleaning up

Minor Spills	 Drains for storage or use areas should have retention basins for pH adjustments and dilution of spills before discharge or disposal of material. Check regularly for spills and leaks. Clean up all spills immediately. Avoid breathing vapours and contact with skin and eyes. Control personal contact with the substance, by using protective equipment. Contain and absorb spill with sand, earth, inert material or vermiculite. Wipe up. Place in a suitable, labelled container for waste disposal.
Major Spills	#

Personal Protective Equipment advice is contained in Section 8 of the SDS.

SECTION 7 HANDLING AND STORAGE

Precautions for safe handling

Safe handling	 Avoid all personal contact, including inhalation. Wear protective clothing when risk of exposure occurs. Use in a well-ventilated area. WARNING: To avoid violent reaction, ALWAYS add material to water and NEVER water to material. Avoid smoking, naked lights or ignition sources. Avoid contact with incompatible materials. When handling, DO NOT eat, drink or smoke. Keep containers securely sealed when not in use. Avoid physical damage to containers. Always wash hands with soap and water after handling. Work clothes should be laundered separately. Launder contaminated clothing before re-use. Use good occupational work practice. Observe manufacturer's storage and handling recommendations contained within this SDS. Atmosphere should be regularly checked against established exposure standards to ensure safe working conditions are maintained.
Other information	 Store in original containers. Keep containers securely sealed. Store in a cool, dry, well-ventilated area. Store away from incompatible materials and foodstuff containers. Protect containers against physical damage and check regularly for leaks. Observe manufacturer's storage and handling recommendations contained within this SDS.

Page 4 of 10

Suitable container	 Lined metal can, lined metal pail/ can. Plastic pail. Polyliner drum. Packing as recommended by manufacturer. Check all containers are clearly labelled and free from leaks. For low viscosity materials Drums and jerricans must be of the non-removable head type. Where a can is to be used as an inner package, the can must have a screwed enclosure. For materials with a viscosity of at least 2680 cSt. (23 deg. C) and solids (between 15 C deg. and 40 deg C.): Removable head packaging; Cans with friction closures and low pressure tubes and cartridges may be used. - Where combination packages are used, and the inner packages are of glass, porcelain or stoneware, there must be sufficient inert cushioning material in contact with inner and outer packages unless the outer packaging is a close fitting moulded plastic box and the substances are not incompatible with the plastic. Inorganic acids are generally soluble in water with the release of hydrogen ions. The resulting solutions have pH's of less than 7.0.
Storage incompatibility	 Inorganic acids are generally solution in water with the release of hydrogen toris. The resulting solutions have pris of less than 7.0. Inorganic acids neutralise chemical bases (for example: amines and inorganic hydroxides) to form salts - neutralisation can generate dangerously large amounts of heat in small spaces. The dissolution of inorganic acids in water or the dilution of their concentrated solutions with additional water may generate significant heat. The addition of water to inorganic acids often generates sufficient heat in the small region of mixing to cause some of the water to boil explosively. The resulting "bumping" can spatter the acid. Inorganic acids react with active metals, including such structural metals as aluminum and iron, to release hydrogen, a flammable gas. Inorganic acids react with cyanide compounds to release of organic compounds. Inorganic acids generate flammable and/or toxic gases in contact with dithiocarbamates, isocyanates, mercaptans, nitrides, nitriles, sulfides, and strong reducing agents. Additional gas-generating reactions occur with sulfites, nitrites, thiosulfates (to give H2S and SO3), dithionites (SO2), and even carbonates. Acids often catalyse (increase the rate of) chemical reactions.

SECTION 8 EXPOSURE CONTROLS / PERSONAL PROTECTION

Control parameters

OCCUPATIONAL EXPOSURE LIMITS (OEL)

INGREDIENT DATA

Source	Ingredient	Material name	TWA	STEL	Peak	Notes
US OSHA Permissible Exposure Levels (PELs) - Table Z1	nitric acid	Nitric acid	5 mg/m3 / 2 ppm	10 mg/m3 / 4 ppm	Not Available	TLV® Basis: URT & eye irr; dental erosion
US NIOSH Recommended Exposure Limits (RELs)	nitric acid	Aqua fortis, Engravers acid, Hydrogen nitrate, Red furning nitric acid (RFNA), White furning nitric acid (WFNA)	5 mg/m3 / 2 ppm	4 ppm	Not Available	Not Available
US ACGIH Threshold Limit Values (TLV)	nitric acid	Nitric acid	2 ppm	Not Available	Not Available	Not Available
US NIOSH Recommended Exposure Limits (RELs)	antimony	Antimony metal, Antimony powder, Stibium	0.5 mg/m3	Not Available	Not Available	[*Note: The REL also applies to other antimony compounds (as Sb).]

EMERGENCY LIMITS

Ingredient	Material name	TEEL-1	TEEL-2	TEEL-3	
nitric acid	Nitric acid	Not Available	Not Available	Not Available	
antimony	Antimony	1.5 mg/m3	13 mg/m3	80 mg/m3	
tartaric acid	Tartaric acid	1.6 mg/m3	17 mg/m3	100 mg/m3	
Ingredient	Original IDLH		Revised IDLH		
nitric acid	100 ppm		25 ppm		
water	Not Available		Not Available		
antimony	80 mg/m3		50 mg/m3		
tartaric acid	Not Available		Not Available		

Exposure controls

Appropriate engineering controls	Engineering controls are used to remove a hazard or place a barrier between the worker and the hazard. Well-designed engineering controls can be highly effective in protecting workers and will typically be independent of worker interactions to provide this high level of protection. The basic types of engineering controls are: Process controls which involve changing the way a job activity or process is done to reduce the risk. Enclosure and/or isolation of emission source which keeps a selected hazard "physically" away from the worker and ventilation that strategically "adds" and "removes" air in the work environment. Ventilation can remove or dilute an air contaminant if designed properly. The design of a ventilation system must match the particular process and chemical or contaminant in use. Employers may need to use multiple types of controls to prevent employee overexposure. Local exhaust ventilation usually required. If risk of overexposure exists, wear approved respirator. Correct fit is essential to obtain adequate protection. Supplied-air type respirator may be required in special circumstances. Correct fit is essential to ensure adequate protection. An approved self contained breathing apparatus (SCBA) may be required in some situations. Provide adequate ventilation in warehouse or closed storage area. Air contaminants generated in the workplace possess varying "escape" velocities which, in
-------------------------------------	--

CLP Spike Standard 2

	Type of Contaminant:	Air Speed:		
	solvent, vapours, degreasing etc., evaporating from tank (in still air).			
	aerosols, fumes from pouring operations, intermittent container filling, low speed conveyer transfers, welding, spray drift, plating acid fumes, pickling (released at low velocity into zone of active generation)	0.5-1 m/s (100-200 f/min.)		
	direct spray, spray painting in shallow booths, drum filling, conveyer loading, crusher dusts, gas discharge (active generation into 2 cone of rapid air motion) 1-2.5 m/s (2 f/min.)			
	grinding, abrasive blasting, tumbling, high speed wheel generated dusts (released at high initial velocity into zone of very high rapid 2.5-10 i f/min.)			
	Within each range the appropriate value depends on:			
	Lower end of the range Upper end of the range			
	1: Room air currents minimal or favourable to capture 1: Disturbing room air currents			
	2: Contaminants of low toxicity or of nuisance value only. 2: Contaminants of high toxicity			
	3: Intermittent, low production. 3: High production, heavy use			
	4: Large hood or large air mass in motion 4: Small hood-local control only	,		
	solvents generated in a tank 2 meters distant from the extraction point. Other mechanical considerations, producing performance defin apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when extraction systems are installed			
Personal protection				
Personal protection	 apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when extraction systems are installed image: the system in the system in the original intervence of the system intervence of the	or used. tacles are not sufficient aterial may be under the protection. describing the wearing of adsorption for the class of bible equipment should be ble. Lens should be remov		
	 apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when extraction systems are installed image: the essential that theoretical air velocities are multiplied by factors of 10 or more when extraction systems are installed image: the essential that theoretical air velocities are multiplied by factors of 10 or more when extraction systems are installed image: the essential that theoretical air velocities are multiplied by factors of 10 or more when extraction systems are installed image: Safety glasses with unperforated side shields may be used where continuous eye protection is desirable, as in laboratories; spect where complete eye protection is needed such as when handling bulk-quantities, where there is a danger of splashing, or if the m pressure. image: Chemical goggles.whenever there is a danger of the material coming in contact with the eyes; goggles must be properly fitted. image: Full face shield (20 cm, 8 in minimum) may be required for supplementary but never for primary protection of eyes; these afford face. image: Contact lenses may pose a special hazard; soft contact lenses may absorb and concentrate irritants. A written policy document, lenses or restrictions on use, should be created for each workplace or task. This should include a review of lens absorption and a chemicals in use and an account of injury experience. Medical and first-aid personnel should be trained in their removal and suita readily available. In the event of chemical exposure, begin eye irrigation immediately and remove contact lens as soon as practical provides and suita readily available. In the event of chemical exposure, begin eye irrigation immediately and remove contact lens as soon as practical provides and performediately and remove contact lens as soon as practical performediately and remove contact lens as soon as practical performediately and remove contact lens as soon as practical performediately a	or used. tacles are not sufficient aterial may be under the protection. describing the wearing of adsorption for the class of bible equipment should be ble. Lens should be remov		
Eye and face protection	 apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when extraction systems are installed <i>i i i i i i i i i i</i>	or used. tacles are not sufficient aterial may be under the protection. describing the wearing of adsorption for the class of bable equipment should be ble. Lens should be remo		
Eye and face protection	 apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when extraction systems are installed apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when extraction systems are installed Safety glasses with unperforated side shields may be used where continuous eye protection is desirable, as in laboratories; spect where complete eye protection is needed such as when handling bulk-quantities, where there is a danger of splashing, or if the m pressure. Chemical goggles whenever there is a danger of the material coming in contact with the eyes; goggles must be properly fitted. Full face shield (20 cm, 8 in minimum) may be required for supplementary but never for primary protection of eyes; these afford face shields. Contact lenses may pose a special hazard; soft contact lenses may absorb and concentrate irritants. A written policy document, i lenses or restrictions on use, should be created for each workplace or task. This should include a review of lens absorption and a chemicals in use and an account of injury experience. Medical and first-aid personnel should be trained in their removal and suitar readily available. In the event of chemical exposure, begin eye irrigation immediately and remove contact lens as soon as practica at the first signs of eye redness or irritation - lens should be removed in a clean environment only after workers have washed ham Current Intelligence Bulletin 59], [AS/NZS 1336 or national equivalent] See Hand protection below Elbow length PVC gloves 	or used. tacles are not sufficient aterial may be under the protection. describing the wearing of adsorption for the class of bable equipment should be ble. Lens should be remo		
Eye and face protection Skin protection Hands/feet protection	 apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when extraction systems are installed <i>Were complete experimental of the state of</i>	or used. tacles are not sufficient aterial may be under the protection. describing the wearing of adsorption for the class of bable equipment should be ble. Lens should be remo		

Respiratory protection

Type A Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

SECTION 9 PHYSICAL AND CHEMICAL PROPERTIES

Information on basic physical and chemical properties

Appearance	Not Available		
Physical state	Liquid	Relative density (Water = 1)	Not Available
Odour	Not Available	Partition coefficient n-octanol / water	Not Available
Odour threshold	Not Available	Auto-ignition temperature (°C)	Not Available
pH (as supplied)	<2	Decomposition temperature	Not Available
Melting point / freezing point (°C)	Not Available	Viscosity (cSt)	Not Available
Initial boiling point and boiling range (°C)	Not Available	Molecular weight (g/mol)	Not Available
Flash point (°C)	Not Available	Taste	Not Available

Evaporation rate	Not Available	Explosive properties	Not Available
Flammability	Not Available	Oxidising properties	Not Available
Upper Explosive Limit (%)	Not Available	Surface Tension (dyn/cm or mN/m)	Not Available
Lower Explosive Limit (%)	Not Available	Volatile Component (%vol)	Not Available
Vapour pressure (kPa)	Not Available	Gas group	Not Available
Solubility in water (g/L)	Miscible	pH as a solution (1%)	Not Available
Vapour density (Air = 1)	Not Available	VOC g/L	Not Available

SECTION 10 STABILITY AND REACTIVITY

Reactivity	See section 7
Chemical stability	Contact with alkaline material liberates heat
Possibility of hazardous reactions	See section 7
Conditions to avoid	See section 7
Incompatible materials	See section 7
Hazardous decomposition products	See section 5

SECTION 11 TOXICOLOGICAL INFORMATION

Information on toxicological effects

Inhaled	The material can cause respiratory irritation in some persons. The body's response to such irritation can cause further lung damage. Corrosive acids can cause irritation of the respiratory tract, with coughing, choking and mucous membrane damage. There may be dizziness, headache, nausea and weakness. The material has NOT been classified by EC Directives or other classification systems as "harmful by inhalation". This is because of the lack of corroborating animal or human evidence.				
Ingestion	Ingestion of acidic corrosives may produce burns around and in the mouth, the throat and oesophagus. Immediate pain and difficulties in swallowing and speaking may also be evident. The material has NOT been classified by EC Directives or other classification systems as "harmful by ingestion". This is because of the lack of corroborating animal or human evidence.				
Skin Contact	Skin contact with acidic corrosives may result in pain and burns; these may be deep with distinct edges and may heal slowly with the formation of scar tissue. Skin contact is not thought to have harmful health effects (as classified under EC Directives); the material may still produce health damage following entry through wounds, lesions or abrasions. Open cuts, abraded or irritated skin should not be exposed to this material Entry into the blood-stream, through, for example, cuts, abrasions or lesions, may produce systemic injury with harmful effects. Examine the skin prior to the use of the material and ensure that any external damage is suitably protected.				
Eye	If applied to the eyes, this material causes severe eye damage. Direct eye contact with acid corrosives may produce pain, tears, sensitivity to lig completely.	ght and burns. Mild burns of the e	pithelia generally recover rapidly and		
Chronic	Repeated or prolonged exposure to acids may result in the erosion of teeth, swelling and/or ulceration of mouth lining. Irritation of airways to lung, with cough, and inflammation of lung tissue often occurs. Long-term exposure to respiratory irritants may result in airways disease, involving difficulty breathing and related whole-body problems. Substance accumulation, in the human body, may occur and may cause some concern following repeated or long-term occupational exposure.				
CLP Spike Standard 2	TOXICITY IRRITATION				
	Not Available	Not Available			
	тохісіту		IRRITATION		
nitric acid	Inhalation (rat) LC50: 625 ppm/1h*t ^[2]		Not Available		
	TOXICITY	IRRITATION			
water	Not Available Not Available				
	TOXICITY		IRRITATION		
antimony	Dermal (rabbit) LD50: >8300 mg/kg ^[1]	Not Available			
	Oral (rat) LD50: 100 mg/kg ^[2]				
	ΤΟΧΙΟΙΤΥ		IRRITATION		
tartaric acid	dermal (rat) LD50: >2000 mg/kg ^[1]		Not Available		
	Oral (rat) LD50: ca.920 mg/kg ^[1]				

1. Value obtained from Europe ECHA Registered Substances - Acute toxicity 2.* Value obtained from manufacturer's SDS. Unless otherwise specified data

Page 7 of 10

CLP Spike Standard 2

	extracted from RTECS - Register of Toxic Effect of chemical Substa	ances		
NITRIC ACID	For acid mists, aerosols, vapours Test results suggest that eukaryotic cells are susceptible to genetic. The material may produce severe irritation to the eye causing prono The material may produce respiratory tract irritation, and result in da The material may cause severe skin irritation after prolonged or repe vesicles, scaling and thickening of the skin. Oral (?) LD50: 50-500 mg/kg * [Various Manufacturers]	unced inflammation. amage to the lung including re	educed lung function.	
WATER	No significant acute toxicological data identified in literature search	No significant acute toxicological data identified in literature search.		
TARTARIC ACID	Convulsions, haemorrhage recorded.			
NITRIC ACID & TARTARIC ACID	Asthma-like symptoms may continue for months or even years after e	exposure to the material ends.		
Acute Toxicity	0	Carcinogenicity	0	
Skin Irritation/Corrosion	¥	Reproductivity	0	
Serious Eye Damage/Irritation	✓	STOT - Single Exposure	0	
Respiratory or Skin sensitisation	⊗ st	OT - Repeated Exposure	0	
Mutagenicity	0	Aspiration Hazard	\otimes	

Data available to make classification

O – Data Not Available to make classification

SECTION 12 ECOLOGICAL INFORMATION

Toxicity ENDPOINT **TEST DURATION (HR)** SPECIES VALUE SOURCE CLP Spike Standard 2 Not Applicable Not Applicable Not Applicable Not Applicable Not Applicable ENDPOINT **TEST DURATION (HR)** SPECIES VALUE SOURCE nitric acid NOEC 16 Crustacea 107mg/L 4 ENDPOINT SPECIES VALUE SOURCE TEST DURATION (HR) water Not Applicable Not Applicable Not Applicable Not Applicable Not Applicable ENDPOINT TEST DURATION (HR) SPECIES VALUE SOURCE LC50 Fish 96 0.93mg/L 2 EC50 2 48 Crustacea 1mg/L antimony 2 EC50 72 Algae or other aquatic plants >2.4mg/L EC50 96 Crustacea 0.5mg/L 2 2 NOEC 720 Fish >0.0075mg/L ENDPOINT TEST DURATION (HR) SPECIES VALUE SOURCE LC50 96 Fish 21450.46422mg/L 3 tartaric acid EC50 96 Algae or other aquatic plants 434.65983mg/L 3 EC50 384 3 Crustacea 8837.885mg/L 4 NOEC 16 Crustacea 135mg/L Extracted from 1. IUCLID Toxicity Data 2. Europe ECHA Registered Substances - Ecotoxicological Information - Aquatic Toxicity 3. EPIWIN Suite V3.12 Legend:

Ecotoxicity:

The tolerance of water organisms towards pH margin and variation is diverse. Recommended pH values for test species listed in OECD guidelines are between 6.0 and almost 9. Acute testing with fish showed 96h-LC50 at about pH 3.5

(Japan) - Bioconcentration Data 7. METI (Japan) - Bioconcentration Data 8. Vendor Data

(QSAR) - Aquatic Toxicity Data (Estimated) 4. US EPA, Ecotox database - Aquatic Toxicity Data 5. ECETOC Aquatic Hazard Assessment Data 6. NITE

Prevent, by any means available, spillage from entering drains or water courses.

DO NOT discharge into sewer or waterways.

Persistence and degradability

Ingredient	Persistence: Water/Soil Persistence: Air		
water	LOW	LOW	
tartaric acid	LOW	LOW	

Chemwatch: 9-405982	Page 8 of 10	Issue Date: 06/03/2017
Catalogue number: CLP-SP-2	CLP Spike Standard 2	Print Date: 06/03/2017
Version No: 1.1		

Bioaccumulative potential

Ingredient	Bioaccumulation
water	LOW (LogKOW = -1.38)
tartaric acid	LOW (LogKOW = -1.0017)

Mobility in soil

Ingredient	Mobility
water	LOW (KOC = 14.3)
tartaric acid	HIGH (KOC = 1)

SECTION 13 DISPOSAL CONSIDERATIONS

Waste treatment methods

Product / Packaging disposal	 Recycle wherever possible. Consult manufacturer for recycling options or consult local or regional waste management authority for disposal if no suitable treatment or disposal facility can be identified. Treat and neutralise at an approved treatment plant. Treatment should involve: Neutralisation with soda-ash or soda-lime followed by: burial in a land-fill specifically licensed to accept chemical and / or pharmaceutical wastes or Incineration in a licensed apparatus (after admixture with suitable combustible material).
	Decontaminate empty containers with 5% aqueous sodium hydroxide or soda ash, followed by water. Observe all label safeguards until containers are cleaned and destroyed.

SECTION 14 TRANSPORT INFORMATION

Labels Required



NO

Marine Pollutant

Land transport (DOT)

UN number	3264			
UN proper shipping name	Corrosive liquid, acidic, inorganic, n.o.s.			
Transport hazard class(es)	Class8SubriskNot Applicable			
Packing group	ll			
Environmental hazard	Not Applicable			
Special precautions for user	Hazard Label8Special provisions386, B2, IB2, T11, TP2, TP27			

Air transport (ICAO-IATA / DGR)

UN number	3264			
UN proper shipping name	Corrosive liquid, acidic, inorganic, n.o.s. *			
Transport hazard class(es)	ICAO/IATA Class8ICAO / IATA SubriskNot ApplicableERG Code8L			
Packing group	II			
Environmental hazard	Not Applicable			
Special precautions for user	Special provisions Cargo Only Packing Instructions Cargo Only Maximum Qty / Pack Passenger and Cargo Packing Instructions Passenger and Cargo Maximum Qty / Pack Passenger and Cargo Limited Quantity Packing Instruction Passenger and Cargo Limited Maximum Qty / Pack	A3A803 855 30 L 851 1 L 5 Y840 0.5 L		

Version No: 1.1

Sea transport (IMDG-Code / GGVSee)

UN number	3264			
UN proper shipping name	CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S.			
Transport hazard class(es)	IMDG Class8IMDG SubriskNot Applicable			
Packing group	I			
Environmental hazard	Not Applicable			
Special precautions for user	EMS NumberF-A, S-BSpecial provisions274Limited Quantities1 L			

Transport in bulk according to Annex II of MARPOL and the IBC code

Not Applicable

SECTION 15 REGULATORY INFORMATION

Safety, health and environmental regulations / legislation specific for the substance or mixture

NITRIC ACID(7697-37-2) IS FOUND ON THE FOLLOWING REGULATORY LISTS

International Air Transport Association (IATA) Dangerous Goods Regulations - Prohibited List	US - Vermont Permissible Exposure Limits Table Z-1-A Final Rule Limits for Air Contaminants	
Passenger and Cargo Aircraft	US - Vermont Permissible Exposure Limits Table Z-1-A Transitional Limits for Air	
US - Alaska Limits for Air Contaminants	Contaminants	
US - California OEHHA/ARB - Acute Reference Exposure Levels and Target Organs (RELs)	US - Washington Permissible exposure limits of air contaminants	
US - California Permissible Exposure Limits for Chemical Contaminants	US - Washington Toxic air pollutants and their ASIL, SQER and de minimis emission values	
US - Hawaii Air Contaminant Limits	US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants	
US - Idaho - Limits for Air Contaminants	US ACGIH Threshold Limit Values (TLV)	
US - Massachusetts - Right To Know Listed Chemicals	US CWA (Clean Water Act) - List of Hazardous Substances	
US - Michigan Exposure Limits for Air Contaminants	US EPCRA Section 313 Chemical List	
US - Minnesota Permissible Exposure Limits (PELs)	US NIOSH Recommended Exposure Limits (RELs)	
US - Oregon Permissible Exposure Limits (Z-1)	US OSHA Permissible Exposure Levels (PELs) - Table Z1	
US - Pennsylvania - Hazardous Substance List	US SARA Section 302 Extremely Hazardous Substances	
US - Rhode Island Hazardous Substance List	US Toxic Substances Control Act (TSCA) - Chemical Substance Inventory	
US - Tennessee Occupational Exposure Limits - Limits For Air Contaminants		
WATER(7732-18-5) IS FOUND ON THE FOLLOWING REGULATORY LISTS		
US - Pennsylvania - Hazardous Substance List	US Toxic Substances Control Act (TSCA) - Chemical Substance Inventory	
ANTIMONY(7440-36-0) IS FOUND ON THE FOLLOWING REGULATORY LISTS		
US - Alaska Limits for Air Contaminants	US - Vermont Permissible Exposure Limits Table Z-1-A Transitional Limits for Air	
	US - Vermont Permissible Exposure Limits Table Z-1-A Transitional Limits for Air Contaminants	
US - Alaska Limits for Air Contaminants		
US - Alaska Limits for Air Contaminants US - California Permissible Exposure Limits for Chemical Contaminants	Contaminants	
US - Alaska Limits for Air Contaminants US - California Permissible Exposure Limits for Chemical Contaminants US - Hawaii Air Contaminant Limits	Contaminants US - Washington Permissible exposure limits of air contaminants	
US - Alaska Limits for Air Contaminants US - California Permissible Exposure Limits for Chemical Contaminants US - Hawaii Air Contaminant Limits US - Idaho - Limits for Air Contaminants	Contaminants US - Washington Permissible exposure limits of air contaminants US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants	
US - Alaska Limits for Air Contaminants US - California Permissible Exposure Limits for Chemical Contaminants US - Hawaii Air Contaminant Limits US - Idaho - Limits for Air Contaminants US - Massachusetts - Right To Know Listed Chemicals	Contaminants US - Washington Permissible exposure limits of air contaminants US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants US ACGIH Threshold Limit Values (TLV)	
US - Alaska Limits for Air Contaminants US - California Permissible Exposure Limits for Chemical Contaminants US - Hawaii Air Contaminant Limits US - Idaho - Limits for Air Contaminants US - Massachusetts - Right To Know Listed Chemicals US - Michigan Exposure Limits for Air Contaminants	Contaminants US - Washington Permissible exposure limits of air contaminants US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants US ACGIH Threshold Limit Values (TLV) US Clean Air Act - Hazardous Air Pollutants	
US - Alaska Limits for Air Contaminants US - California Permissible Exposure Limits for Chemical Contaminants US - Hawaii Air Contaminant Limits US - Idaho - Limits for Air Contaminants US - Massachusetts - Right To Know Listed Chemicals US - Michigan Exposure Limits for Air Contaminants US - Minnesota Permissible Exposure Limits (PELs)	Contaminants US - Washington Permissible exposure limits of air contaminants US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants US ACGIH Threshold Limit Values (TLV) US Clean Air Act - Hazardous Air Pollutants US CWA (Clean Water Act) - Priority Pollutants	
US - Alaska Limits for Air Contaminants US - California Permissible Exposure Limits for Chemical Contaminants US - Hawaii Air Contaminant Limits US - Idaho - Limits for Air Contaminants US - Massachusetts - Right To Know Listed Chemicals US - Michigan Exposure Limits for Air Contaminants US - Minnesota Permissible Exposure Limits (PELs) US - Oregon Permissible Exposure Limits (Z-1)	Contaminants US - Washington Permissible exposure limits of air contaminants US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants US ACGIH Threshold Limit Values (TLV) US Clean Air Act - Hazardous Air Pollutants US CWA (Clean Water Act) - Priority Pollutants US CWA (Clean Water Act) - Toxic Pollutants	
US - Alaska Limits for Air Contaminants US - California Permissible Exposure Limits for Chemical Contaminants US - Hawaii Air Contaminant Limits US - Idaho - Limits for Air Contaminants US - Massachusetts - Right To Know Listed Chemicals US - Michigan Exposure Limits for Air Contaminants US - Michigan Exposure Limits for Air Contaminants US - Minnesota Permissible Exposure Limits (PELs) US - Oregon Permissible Exposure Limits (Z-1) US - Pennsylvania - Hazardous Substance List	Contaminants US - Washington Permissible exposure limits of air contaminants US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants US ACGIH Threshold Limit Values (TLV) US Clean Air Act - Hazardous Air Pollutants US CWA (Clean Water Act) - Priority Pollutants US CWA (Clean Water Act) - Toxic Pollutants US EPCRA Section 313 Chemical List	
US - Alaska Limits for Air Contaminants US - California Permissible Exposure Limits for Chemical Contaminants US - Hawaii Air Contaminant Limits US - Idaho - Limits for Air Contaminants US - Massachusetts - Right To Know Listed Chemicals US - Michigan Exposure Limits for Air Contaminants US - Michigan Exposure Limits for Air Contaminants US - Minnesota Permissible Exposure Limits (PELs) US - Oregon Permissible Exposure Limits (Z-1) US - Pennsylvania - Hazardous Substance List US - Rhode Island Hazardous Substance List	Contaminants US - Washington Permissible exposure limits of air contaminants US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants US ACGIH Threshold Limit Values (TLV) US Clean Air Act - Hazardous Air Pollutants US CWA (Clean Water Act) - Priority Pollutants US CWA (Clean Water Act) - Toxic Pollutants US EPCRA Section 313 Chemical List US NIOSH Recommended Exposure Limits (RELs)	
US - Alaska Limits for Air Contaminants US - California Permissible Exposure Limits for Chemical Contaminants US - Hawaii Air Contaminant Limits US - Idaho - Limits for Air Contaminants US - Massachusetts - Right To Know Listed Chemicals US - Michigan Exposure Limits for Air Contaminants US - Michigan Exposure Limits for Air Contaminants US - Minnesota Permissible Exposure Limits (PELs) US - Oregon Permissible Exposure Limits (Z-1) US - Pennsylvania - Hazardous Substance List US - Rhode Island Hazardous Substance List US - Tennessee Occupational Exposure Limits - Limits For Air Contaminants	Contaminants US - Washington Permissible exposure limits of air contaminants US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants US ACGIH Threshold Limit Values (TLV) US Clean Air Act - Hazardous Air Pollutants US CWA (Clean Water Act) - Priority Pollutants US CWA (Clean Water Act) - Toxic Pollutants US EPCRA Section 313 Chemical List US NIOSH Recommended Exposure Limits (RELs) US OSHA Permissible Exposure Levels (PELs) - Table Z1	
US - Alaska Limits for Air Contaminants US - California Permissible Exposure Limits for Chemical Contaminants US - Hawaii Air Contaminant Limits US - Idaho - Limits for Air Contaminants US - Massachusetts - Right To Know Listed Chemicals US - Michigan Exposure Limits for Air Contaminants US - Minnesota Permissible Exposure Limits (PELs) US - Oregon Permissible Exposure Limits (Z-1) US - Pennsylvania - Hazardous Substance List US - Rhode Island Hazardous Substance List US - Tennessee Occupational Exposure Limits - Limits For Air Contaminants US - Vermont Permissible Exposure Limits Table Z-1-A Final Rule Limits for Air Contaminants	Contaminants US - Washington Permissible exposure limits of air contaminants US - Wyoming Toxic and Hazardous Substances Table Z1 Limits for Air Contaminants US ACGIH Threshold Limit Values (TLV) US Clean Air Act - Hazardous Air Pollutants US CWA (Clean Water Act) - Priority Pollutants US CWA (Clean Water Act) - Toxic Pollutants US EPCRA Section 313 Chemical List US NIOSH Recommended Exposure Limits (RELs) US OSHA Permissible Exposure Levels (PELs) - Table Z1	

Federal Regulations

Superfund Amendments and Reauthorization Act of 1986 (SARA)

SECTION 311/312 HAZARD CATEGORIES

Immediate (acute) health hazard	Yes		
Delayed (chronic) health hazard	No		
Fire hazard	No		
Pressure hazard	No		
Reactivity hazard	No		
US. EPA CERCLA HAZARDOUS SUBSTANCES AND REPORTABLE QUANTITIES (40 CFR 302.4)			

Name	Reportable Quantity in Pounds (Ib)	Reportable Quantity in kg	
Nitric acid	1000	454	

Chemwatch: 9-405982		Page 10 of 10		Issue Date: 06/03/2017
Catalogue number: CLP-SP-2		CLP Spike Standard 2		Print Date: 06/03/2017
Version No: 1.1				
Antimony	5000		2270	
State Regulations				
US. CALIFORNIA PROPOSITION	DN 65			
National Inventory	Status			
Australia - AICS	Y			
Canada - DSL	Y			
Canada - NDSL	N (water; antimony; tartaric acid; nitric acid)			
China - IECSC	Y			
Europe - EINEC / ELINCS / NLP	Υ			
Japan - ENCS	N (water; antimony; tartaric acid; nitric acid)			
Korea - KECI	Y			
New Zealand - NZIoC	Y			
Philippines - PICCS	Y			
USA - TSCA	Y			
Legend:	Y = All ingredients are on the inventory N = Not determined or one or more ingredient	nts are not on the inventory and are not exemp	ot from listing(see specific ingredien	ts in brackets)

SECTION 16 OTHER INFORMATION

Other information

Classification of the preparation and its individual components has drawn on official and authoritative sources as well as independent review by the Chemwatch Classification committee using available literature references.

The SDS is a Hazard Communication tool and should be used to assist in the Risk Assessment. Many factors determine whether the reported Hazards are Risks in the workplace or other settings. Risks may be determined by reference to Exposures Scenarios. Scale of use, frequency of use and current or available engineering controls must be considered.

Definitions and abbreviations

PC-TWA: Permissible Concentration-Time Weighted Average

PC-STEL: Permissible Concentration-Short Term Exposure Limit

- IARC: International Agency for Research on Cancer
- ACGIH: American Conference of Governmental Industrial Hygienists

STEL: Short Term Exposure Limit

TEEL: Temporary Emergency Exposure Limit_{\circ}

- IDLH: Immediately Dangerous to Life or Health Concentrations OSF: Odour Safety Factor NOAEL :No Observed Adverse Effect Level
- LOAEL: Lowest Observed Adverse Effect Level
- TLV: Threshold Limit Value
- I OD. Limit Of Detection
- OTV: Odour Threshold Value
- **BCF: BioConcentration Factors**
- BEI: Biological Exposure Index

This document is copyright.

Apart from any fair dealing for the purposes of private study, research, review or criticism, as permitted under the Copyright Act, no part may be reproduced by any process without written permission from CHEMWATCH.

TEL (+61 3) 9572 4700.